As	SSIGNMENT
om;Date;	545714618 Yr Regn: 2016, NOV
stimated Cost:	Veh No: SHD 714618 Yr Regn: 2016, NoV  Type: M.Car / M.Cycle / Bus / Van / Lorry / Faxi / Prime Mover /  Truck / Trailer or
D / TR/WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
o Inspect Vehicle No:	14. moder 140 c.c (683)
t Workshop m/s	A/C: insured / Std / NI / NA
f	Sp.Reading Colour T/Radio: Insured / Std / NI / NA
nsured:	
olicy No.	Eng/No: C/No: KMHLB4(UMH 49691)
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: (Ni) / S/Rim / STD A/Rim qr
	Tyre Size: F: 205 6 0 16 6
(Policy Condition)	R:
	DIS BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or westlate.
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent?: Yes or No	R/Bal. 0 mm R/Bal. 0 mm
GIA / PR Seen: Consistent? : Yes or No	L/Balmm L/Balmm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 14/6/22
Lum Sum: % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle; IN /	
	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time   Action / Instruction	
1	·
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
1) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
<sup>2)</sup> Ade	Fee: Site Insp (\$ )_s+Rs_s
<u></u>	
Reprofesional:	: Interview (\$ ) Photos
The second of th	:Tech. Invs (\$) Others
Lump Sum / LB.A: (%	: Weekend (\$

## SAS-KIV

## COMFORTDELGRO ENGINEERING PTE LTD

## **REPAIR ESTIMATE**

Effective Date: 1 Nov 2020

DATE:

13.06.2022

MODEL:

Hyundai i40

VEHICLE NO.: SHD7146B

INSURANCE: CHINA TAIPING

MVA: LIMTS

ART NO.	DESCRIPTION	QTY	UN	IIT PRICE	AMOUNT	
	Rear Bumper	1			\$ 553.004	He
	Rear Bumper Under Cover	1			\$ 228.00	
	Rear Bumper Clips	10	\$	2.20	\$ 22.00	J. C.
	SUB TOTAL				\$ 803.00	
	LESS 20%				\$ 160.60	
	DISCOUNTED TOTAL				\$ 642.40	-
	Rear Bumper Advertisement Sticker	1			\$ 50.00	NET
	Rear Fender Advertisement Sticker RH/LH	2	\$	100.00	\$ 200.00	NET
	SPARE PARTS TOTAL				\$ 892.40	
	Labour Charge					_
	Panel Beating				\$ 300.00 300.00	2
	Spray Painting Charge				\$ 300.00	2
	R/I Reverse Sensors				\$ 120.00	2 2 3
	TOTAL LABOUR				\$ 720.00	
	ESTIMATE TOTAL			-	\$ 1,612.40	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Paufkin 97415749 W/ 14/6/22 2 1050 2 deys tenfth C/bhanto. wn US Nowy Son repor-

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- · To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 5280 9755 Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508869 383 Sin Ming Drive Singapore 575717

	•	Date/Tir	me: 13.06.2022 13:40	Page : 1		
eam:	ARC Repair TP(CLSO)1	JOB CARD	Sales Order: 4276560	JC NO.305519417		
FOMER 48	COMPORT TRANSPORT		REGN NO.: SHD7146B	MILEAGE		
AS COMFORT TRANSPORTATION PTE FOMER NO. 7010045 RESS 383 SIN MING DRIVE			MAKE: HYUNDAI	FUEL EF  DATE/TIME IN		
(R)	Singapore SINGAPORE 575717 65508755 (O)		10 (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	.06.2022 10:55		
(P) OUNT CA	APPAIO		YR OF MANU. 17.11.2016 CHASSIS CODE KMHLB41UMHU096341	COMPLETION DATE/TIME:		
CONTCA	ARD NO.	The structure of a Committee System Administrator sources committee and accommittee of a Committee System Administrator sources committee and accommittee of the System Administrator sources committee and accommittee and accomm	KMHLB41UMHU096341			
CCide ATUof V	ent Date: 13.06.2022 /el: 3P 13.06.2022	JOB DESCRIPTION				
/NO 0001	LABOR CODE O PB	DESCRI PANEL BEATIN	PTION G-SHD7146B-TP	FRONT		
	9		LEFT SIDE O	RIGHT SIDE		
	Ā		REAR			
KED & PAS	SED OUT BY:			Makes in the contract of the c		
	SERVICE ADVISOR		CUSTOMER'S SI	ONATURE		
ledgement S	Slip	Exit Pass	20010INIER 2 21	GIVALUKE		
√o.: SI	HD7146B LIMTS	Vehicle No.:	71.46B			

fittined to Service Reception upon collection

f Service Advisor

Signature/Date

Name of Service Advisor

Date

To be kept by Security Guard