COMFORTDELGRO

Our Job Ref No : 305519417 Date : 16.06.2022						ENGINEERING ComfortDelGro Engineering Pte Ltd				
FINALIZATION FORM						59 Loyang Drive Singapore 508969 Fax: 6546 8156				
То	: LKK Fax:							C:		
Attn	8									
Vehicle Reg No. : SHD7				7146B		Date of Accident :		nt : 13.06.	13.06.2022	
The	survey	and es	timates of	the repairs of the	above-mer	ntione	d vehicle are	as follows:-		
1.	The r	epair j	ob shall bill		SJA109	5X				
2.	. The finalized amount shall be:									
	(a) Spare Parts after List discount									
	(b) Labour Charges (include advertisement stickers etc,if any)									
	Total for Part-By-Part Repair Cost									
	(c.) Lumpsum Repair (if applicable)									
	Total for Lumpsum repair cost after Less: 20% Final Lumpsum Repair cost								\$1,000.00 \$1,000.00	
			•							
3. 4.	Estimated normal period for repairs: 2 working days. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days									
5. Thank you for your assi				stance.		We confirm the estimates and finalized amount				
	Signat	ture :		rimp	_	S	iignature 🖫 _	taufik	éh	
	Name : LIMTS				_	Name : Date :		TAUFIKH		
	Tel : 6214839			8				29/7/22	29/7/22	
	Fax	(2)	6546815	6	_					
For C	Official	Use O	nly			_				
	Item			Amount	Docum Attacl Yes or	hed	Confirm By (Signature)		rks	
Rental Rate P/Day			ay		YE	S				
2. Lo	2. Loss of Income Paid			777	N					
3. Survey Fees					-					
4. LTA Search Fee				\$7.49 /\$2.00	Y					
Medical Fees (on behalf of driver, if applicable)										
6 Overrun										

Remarks: