

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. 1001539214
 Claims No. 277221
 Sum Insured: _____ Excess: 1500
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Sent: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKF1P382 Yr Regn: 14/11/18
 Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
 Truck / Trailer or
 Make: Volkswagen Tiguan c.c. 1395
 Colour: Grey A/C: Insured / Std / Nil / NA
 Sp. Reading: 4/5/18 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: WVG2215N15W 963060
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: NII / S/Rim / STD A/Rim or
 Tyre Size: F: 235/55R18
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZ / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Pirelli
 Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. 24/6/22 D.O.I. 24/6/22
 Survey held at Volkswagen
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Roof or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-129K</u>
<u>15/7/22</u>	<u>Final fig \$20,531.19 (red 4996.69, 20%)</u>

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Date/Time, File Return to?

2) 15/7/22-typistReport Format: MerimenLump Sum / L.B.F. (\$ \$20,531.19)Days Of Repair: 9Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Others

TOTAL

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

24/6/2022 @ 1pm (akt)

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details:
Mr
T MURALI
222 BISHAN STREET 23
#06-159
Singapore 570222

Page 1/3
Document no.
Document date 23-06-2022
Customer no. 5211001211
Customer GST-ID 200412212G
Dealer 30001
Job order number 2022018249/ 1
Job order date 23-06-2022
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SKF1038Z	AD14PY	14-11-2018	WVGZZZ5NZJW963060	Tiguan 1.4actHLBMTFR 110TSID6F	35,554

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
9801B001	TO ALIGN LED HEADLIGHT				#1	100.00	107.00
9801B003	B&P WHEEL ALIGNMENT				#1	360.00	385.20
9801B001	R&R RIM & BALANCE				#1	50.00	53.50
5NA807217J GRU	Cover For Bumper Primed	1	pcs.	1,621.35	10.00%	1,459.22	1,561.37
5NA919399 GRU	Sensor Bracket Primed	1	pcs.	16.79	10.00%	15.11	16.17
5NA919400 GRU	Sensor Bracket Primed	1	pcs.	16.79	10.00%	15.11	16.17
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	85.94	10.00%	77.35	82.76
D 822150A1	Bonding Agent For Plastic	1	pcs.	68.85	10.00%	61.97	66.31
5NA805903A 9B9	Spoiler Satin Black	1	pcs.	379.49	10.00%	341.54	365.45
5NA807049A	Guide Piece	1	pcs.	26.71	10.00%	24.04	25.72
5NA807050A	BUMPER SIDE BRACKET LH	1	pcs.	26.71	10.00%	24.04	25.72
5NA853211A 9B9	Guide Piece	1	pcs.	26.71	10.00%	24.04	25.72
5NA853211A 9B9	BUMPER SIDE BRACKET RH	1	pcs.	50.06	10.00%	45.05	48.20
5NC941113E	Trim Satin Black	1	pcs.	50.06	10.00%	45.05	48.20
3C0973737	LHS FOG LAMP SIDE TRIM	1	pcs.	2,349.36	10.00%	2,114.42	2,262.43
5NA821105B	Led Headlight	1	pcs.	21.54	10.00%	19.39	20.75
5NA821135B	LHS H/LAMP	1	pcs.	787.24	10.00%	708.52	758.12
5NA821135B	Flat Contact Housing With H/LAMP WIRE HOUSING	1	pcs.	45.43	10.00%	40.89	43.75
5NA805911AG	Fender	1	pcs.	143.24	10.00%	128.92	137.94
5NA854731E 9B9	RHF FRNDER	1	pcs.	211.10	10.00%	189.99	203.29
3C0853586	Cross Support	1	pcs.	1.84	10.00%	13.25	14.18
5NC857507S 9B9	LHF FENDER BRACKET	1	pcs.	778.02	10.00%	700.22	749.24
5NA857537 GRU	Wheelhouse Liner	1	pcs.	169.34	10.00%	152.41	163.08
5NA857521A	LHS FENDER LINER	1	pcs.	200.33	10.00%	180.30	192.92
5NA831055N	Wheel Cover Satin Black	1	pcs.	2,168.95	10.00%	1,952.06	2,088.70
5NA837701A 5AP	LHS WHEEL ARCH	8	pcs.	241.67	10.00%	217.50	232.73
D 378500A2	Grommet	1	pcs.	43.65	10.00%	39.29	42.04
N 91203801	Rear View Mirror Housing	1	pcs.	5.62	10.00%	10.12	10.83
WHT005504	Mirror Cap Primed	1	pcs.	3.12	10.00%	5.62	6.01
5NA837475E VNH	Mirror Glass	1	pcs.	186.01	10.00%	167.41	179.13
5NA854939AFRYP	Door	1	pcs.	341.02	10.00%	306.92	328.40
	LHS FRT DOOR	1	pcs.				
	Door Seal Outer Black	1	pcs.				
	Alu-Lamin. Insulation	1	pcs.				
	DOOR INSULATION	2	pcs.				
	Bolt With Polygon Socket	2	pcs.				
	Fill. Hd. Screw	1	pcs.				
	Window Slot Seal With Tri	1	pcs.				
	LHF DOOR GLASS OUTER MLDG CHROM	1	pcs.				
	Cover For Door Satin Blac	1	pcs.				
	LHF DOOR LOWER PROTECTOR	1	pcs.				

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

2/3

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details:
Mr
T MURALI
222 BISHAN STREET 23
#06-159
Singapore 570222

Document no.
Document date 23-06-2022
Customer no. 5211001211
Customer GST-ID 200412212G
Dealer 30001
Job order number 2022018249/ 1
Job order date 23-06-2022
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SKF1038Z	AD14PY	14-11-2018	WVGZZZ5NZJW963060	Tiguan 1.4actHLBMTFR 110TSID6F	35,554

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
3C0853586	Grommet	8	pcs.	1.84	10.00% #1	13.25	14.18
5NA833055L	Door LHR DOOR	1	pcs.	2,863.18	10.00% #1	2,576.86	2,757.24
5NA839701A SAP	Door Seal Outer Black	1	pcs.	221.28	10.00% #1	199.15	213.09
D 378500A2	Alu-Lamin. Insulation	1	pcs.	43.65	10.00% #1	39.29	42.04
	DOOR INSULATION						
N 91203801	Bolt With Polygon Socket	2	pcs.	5.62	10.00% #1	10.12	10.83
WHT005504	Fill. Hd. Screw	2	pcs.	3.12	10.00% #1	5.62	6.01
7L6868243	Clip	8	pcs.	1.70	10.00% #1	12.24	13.10
5NA85494AFRYP	Cover For Door Satin Blac	1	pcs.	483.22	10.00% #1	434.90	465.34
	LHR DOOR LOWER PROTECTOR						
5NA601025ABFZZ	Alloy Wheel Black Turned	1	pcs.	2,849.09	10.00% #1	2,564.18	2,743.67
311601361	Rubber Valve	1	pcs.	3.85	10.00% #1	3.47	3.71
	LABOUR	84	pcs.	650.00	#1 2600	3,900.00	4,173.00
	SPRAY PAINT	8	pcs.	600.00	#1 3150	3,600.00	3,852.00
	TRANSFER DOOR MECHANISM	2	pcs.	650.00	#1 650	1,300.00	1,391.00
	MSIG MOTORMAXPLUS OD						
	DOA:22/06/2022						
	EXCESS:						
	SURVEY BY:						

Supp - Trim Glossy alumin LH, fml - RT \$
- Wheel trim (Black) LH, fml - CNT \$

Quotation valid till 30-06-2022

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#1	1,270.00	23,669.74	1,652.12	7%	1,745.78	1,652.12	24,939.74	26,685.52
Total	1,270.00	23,669.74	1,652.12		1,745.78	1,652.12	24,939.74	26,685.52

Steve (LKK)
24/6/22, 2.17p

OD - LH AL
EXMIS-?
PIP

ly RL ly
8-9 ly

Customer

Service Advisor

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before repair work commencing
- To display damaged parts for resurvey
- VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions) subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No alterations/modification(s) is allowed
- Supplier's item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	22/06/2022 16:34 (SGT)
Reported by	Both
Date of Accident	22/06/2022 13:17 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONG BRADDELL ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKF1038Z

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	T MURALI
NRIC No	SXXXX853G
Email Address	murali.tt@gmail.com
Mobile Phone No	(Phone) +65-90672212
Alternative Phone No	+65-90672212

VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	Tiguan
Variant	Tiguan 1.4actHLBMTFR 110TSID6F
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1400

INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	A 300383468 QMY

DRIVER

Name of Driver	T MURALI
NRIC No	SXXXX853G
Date Of Birth	17/06/1978
Occupation	Indoor

Date Of Driving Pass 13/10/2011
 Driving experience 10 YEARS AND 8 MONTHS
 Gender Male
 Mobile Number (Phone) +65-90672212
 Alt. Phone Number +65-90672212
 Email Address murali.tt@gmail.com
 Address 225 upper paya lebar road
 Address complement #13-11
 Postcode 533873
 Is the driver the policyholder? Yes
 If No, Relationship of the Driver with the Insured -
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Change/cross lane
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 1
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No
 Translator's name -
 Translator's ID -
 Translator's phone number -
 Translator's email -
 Original language used in the statement -

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLL784R
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Private car
 Name of Driver REV. LIM KOK HENG
 Contact Number (Phone) +65-96670746

Address *

Address complement *

Postcode *

Insurance Company Name *

Nature Of Damage *

Details of property damaged in accident *

No. Of Passenger (Including Driver) *

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

lll 22/6/2022
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

of 22/6/2022
Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

I was driving along Broadall Road at about 1 pm. For a split second, I accidentally overtook my lane and crossed into the adjacent lane but adjusted back. But at this time there was another car which grazed against mine. This making contact with the side mirror. We stopped. All parties were injured. We exchanged contacts & pictures and agreed to discuss the next step separately.

Declaration

We declare the foregoing particulars are true in every respect.

ell 22/6/2022
 Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

W 22/6/2022
 Witnessed by Reporting Centre Personnel