<u>A</u>	SSIGNMENT
From: Date:	Veh No: YO S960 K Yr Regn: 2022 Mark
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Corp / Taxi / Prime Mover /
OB / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: 40 1366K	Make: MIRWASHI CANTER FEAOL C.C 2998
at Workshop m/s Loutel	
of 8, That give 12	Sp.Reading — A/C: Insured / Std / NI / NA
Insured: Wol	Eng/No:
Policy No.	C/No: PGA D(BA35337 .
Claims No.	Gen. Cond: Good / Pair Poor / Burnt
Sum Insured: Excess: 76A	Steering: Inorder Jammed / Leaked / Burnt or
(Client's Record)	Brake: Incorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: (Nil 7S/Rim / STD A/Rim or
	Tyre Size: F: 18\$15 RUS
(Policy Condition)	R: Las 15 KVJ
Remark: The veh had commenced its N/S 0/	710
repair at the time of inspection.	Тоуо / уоко ог
Bal. or Market Value: (0 2 K	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 7 mm R/Bal. 7/7 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 7 mm L/Bal. 1/7 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 21/66/22 D.O.I. 24/66/27
Lum Sum: % 3 Val.: Yes or No	Survey held at COLOBELL
CA / REV. / REP. / 24 HRS	Des. of Damages Frt) / Rear / O/S / N/S / U/C / Rooftop or
ON ICHEY I REP. I 24 HKS	
Vehicle: IN / O	
Vehicle: IN / O	The U/C / Chassis frame / Body Structure affected due to collision
Date: Person Contacted: Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date: Person Contacted: Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
Date: Person Contacted: Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision
Date: Person Contacted: Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision
Date: Person Contacted: Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision
Date: Person Contacted: Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision
Date: Person Contacted: Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision
Date: Person Contacted: Date / Time Action / Instruction REPANE LIMIT - SQIC	
Date / Time Action / Instruction REPARK LIMIT - SQK ste/Time, File Pass to? : Prell. Report	Days Of Repair:
Date: Person Contacted: Date / Time Action / Instruction REPARE LIMIT - SQK ale/Time, File Pass to? : Preli. Report : Final Report	
Date / Time Action / Instruction REPARE LIMIT - SOK ale/Time, File Pass to? : Preli. Report : Final Report	Days Of Repair: Resurvey No. of Trip: Survey Fee:
Date / Time Action / Instruction REPARE LIMIT - SOK ste/Time, File Pass to? : Final Report : Final Report	Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportation:
Date / Time Action / Instruction REPARE LIMIT - SOIC Ble/Time, File Pass to? : Preli. Report : Final Report ate/Time, File Return to?	Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportation:

Industrial Vehicles. Financial Services. 41,000 Served. And Counting.

Email / Fax No. : CatherineChongKL@goldbell.com.sg

GOLDBELL ENGINEERING PTE LTD

Main Office 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676 Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500 Website: www.goldbell.com.sg Co Reg No 198003963G

: 8 TUAS AVE 18

Page

1 / 3

ESTIMATE

Reg No : YQ5960K Date 23/06/2022

Model : FEA01BR2SDEP CBU MT To UNITED OVERSEAS INSURANCE

LIMITED

Attn.

Attn. **Chassis No** FEA01BA35337 4P10E22602 Office / Mobile **Engine No**

Quotation No. 158957 **Email Address**

Ref. No. : GBE/SVC/SALES-HQ/207-2106

Workshop

D.O.A. From : 21/06/2022 GOLDBELL ENGINEERING PTE LTD

Policy No. : DHOM120064922200 CATHERINECHONGKL Office / Mobile Claim Type OD CLAIM - UNITED

OVERSEAS INSURANCE

Part No	Description	Qty	U/Price			Ext Price
		1	1,012.50	-25	759.38	759.38
		1	390.32	-25	292.74	292.74
		1	621.07	-25	465.80	465.80
	는 지역 경기를 가면 보면 교통하다 아니라 (18.50m) (18.50m) (18.50m) (18.50m)	1	410.38	-25	307.78	307.78
		1	549.75	-25	412.31	412.31
	PANEL, CAB FR CORNER -RH CM/	1	549.75	-25	412.31	412.31
	CAP, MIRROR COVER RH M!	1	43.56	-25	32.67	32.67
	PILLAR, FR RH reperior	1	1,606.60	-25	1,204.95	1,204.95
	MARK, CANTER MAR	1	115.06	-25	86.30	86.30
	MARK,THREE-DIA MARK	1	89.66	-25	67.25	67.25
	PANEL ASSY, FRONT 54	1	2,832.78	-25	2,124.59	2,124.59
	STAY, RR VIEW MIRROR -LH 41	1	497.88	-25	373.41	373.41
	MIRROR, UNDER VIEW CM	1	60.35	-25	45.26	45.26
	COVER, FR BMPR CORNER, LH SCA	1	367.25	-25	275.44	275.44
	COVER, FR BUMPER CORNER, RH SW	1	367.25	-25	275.44	275.44
	GARNISH, HEADLAMP, LH AU	1	189.00	-25	141.75	141.75
	GARNISH, HEADLAMP, RH X	1	189.00	-25	141.75	141.75
	LAMP ASSY, TURN SIGNAL, FR LH	1	229.26	-25	171.95	171.95
	LAMP ASSY, TURN SIGNAL, FR RH	1	229.26	-25	171.95	171.95
	HEADLAMP ASSY, LH	1	696.91	-25	522.68	522.68
	HEADLAMP ASSY,RH C	1	696.91	-25	522.68	522.68
	ARM W/SHLD WIPER	1	121.51	-25	91.13	91.13
	BLADE ASSY, WIPER ~	1	52.77	-25	39.58	39.58
		1	2,942.91	-25	2,207.18	2,207.18
	DUCT,AIR CLEANER INTAKE	1	790.78	-25	593.09	593.09
		PART:	S TOTAL :			11,739.37
	Part No	GLASS, WINDSHIELD CM WEATHERSTRIP, WINDSHIELD MARNISH, FR PANEL CAM GRILLE, RADIATOR CM PANEL, CAB FR CORNER - LH CM PANEL, CAB FR CORNER - RH CAM CAP, MIRROR COVER RH MM! MARK, CANTER MARK, CANTER MARK, CANTER MARK, THREE-DIA MARK, THREE-DIA MIRROR, UNDER VIEW CM COVER, FR BMPR CORNER, LH SM COVER, FR BUMPER CORNER, RH SM GARNISH, HEADLAMP, LH MM LAMP ASSY, TURN SIGNAL, FR RH HEADLAMP ASSY, TURN SIGNAL, FR RH HEADLAMP ASSY, LH CM ARM W/SHLD WIPER CAM BLADE ASSY, WIPER HEATER ASSY ?	GLASS, WINDSHIELD M WEATHERSTRIP, WINDSHIELD M GARNISH, FR PANEL CAM GRILLE, RADIATOR COM PANEL, CAB FR CORNER - LH COM PANEL, CAB FR CORNER - RH CAM CAP, MIRROR COVER RH M PILLAR, FR RH PANEL MARK, CANTER M MARK, CANTER M PANEL ASSY, FRONT M STAY, RR VIEW MIRROR - LH M COVER, FR BMPR CORNER, LH SM COVER, FR BMPR CORNER, LH SM GARNISH, HEADLAMP, LH M LAMP ASSY, TURN SIGNAL, FR RH M LAMP ASSY, TURN SIGNAL, FR RH M HEADLAMP ASSY, LH COM ARM W/SHLD WIPER CAM BLADE ASSY, WIPER M HEATER ASSY DUCT, AIR CLEANER INTAKE 1 1 1 1 1 1 1 1 1 1 1 1 1	GLASS, WINDSHIELD (M) WEATHERSTRIP, WINDSHIELD M 1 390.32 GARNISH, FR PANEL M 1 621.07 GRILLE, RADIATOR (M) 1 410.38 PANEL, CAB FR CORNER -LH (M) 1 549.75 PANEL, CAB FR CORNER -RH CM 1 549.75 CAP, MIRROR COVER RH MM 1 1,606.60 MARK, FR RH FAMILY 1 1,606.60 MARK, CANTER M 1 115.06 MARK, THREE-DIA M 1 89.66 PANEL ASSY, FRONT 1 1 2,832.78 STAY, RR VIEW MIRROR -LH 1 1 497.88 MIRROR, UNDER VIEW CM 1 60.35 COVER, FR BMPR CORNER, LH SM 1 367.25 COVER, FR BUMPER CORNER, RH SM 1 189.00 GARNISH, HEADLAMP, LH M 1 189.00 GARNISH, HEADLAMP, RH 1 1 229.26 LAMP ASSY, TURN SIGNAL, FR LH M 1 229.26 HEADLAMP ASSY, LH CM 1 696.91 HEADLAMP ASSY, RH CM 1 696.91 ARM W/SHLD WIPER CM 1 52.77 HEATER ASSY 7 1 2,942.91	GLASS, WINDSHIELD (M) 1 1,012.50 -25 WEATHERSTRIP, WINDSHIELD 1 390.32 -25 GARNISH, FR PANEL (M) 1 621.07 -25 GRILLE, RADIATOR (M) 1 549.75 -25 PANEL, CAB FR CORNER -LH (M) 1 549.75 -25 PANEL, CAB FR CORNER -RH (M) 1 549.75 -25 CAP, MIRROR COVER RH MI 1 1,606.60 -25 PILLAR, FR RH PARTILL 1 1,606.60 -25 MARK, CANTER (M) 1 15.06 -25 MARK, CANTER (M) 1 15.06 -25 MARK, THREE-DIA 1 15.06 -25 MARK, THREE-DIA 1 19.06 -25 MIRROR, UNDER VIEW (M) 1 60.35 -25 COVER, FR BMPR CORNER, LH 1 1 367.25 -25 COVER, FR BMPR CORNER, LH 1 1 189.00 -25 GARNISH, HEADLAMP, LH M 1 189.00 -25 GARNISH, HEADLAMP, RH M 1 189.00 -25 LAMP ASSY, TURN SIGNAL, FR RH M 1 229.26 -25 LAMP ASSY, TURN SIGNAL, FR RH M 1 229.26 -25 HEADLAMP ASSY, LH (M) 1 696.91 -25 ARM W/SHLD WIPER (M) 1 52.77 -25 BLADE ASSY, WIPER (M) 1 2,942.91 -25 DUCT, AIR CLEANER INTAKE 1 790.78 -25	GLASS, WINDSHIELD (M) WEATHERSTRIP, WINDSHIELD MINDSHIELD MINDSHI

SPECIAL NETT ITEMS

1 IU BRACKET A 1 2 COMPANY STICKER IM

200.00 1 150

PARTS TOTAL:

215.00

15.00













Industrial Vehicles. Financial Services. 41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676 Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500 Website: www.goldbell.com.sg

Co. Reg. No. 198003963G

Page

2 / 3

ESTIMATE

Date

23/06/2022

To

UNITED OVERSEAS INSURANCE

LIMITED

Attn.

From

Office / Mobile

Email Address

Attn.

Office / Mobile

GOLDBELL ENGINEERING PTE LTD CATHERINECHONGKL

Email / Fax No. : CatherineChongKL@goldbell.com.sg

Reg No

: YO5960K

Model

FEA01BR2SDEP CBU MT

Chassis No

FEA01BA35337

Engine No Quotation No. 4P10E22602 158957

Ref. No.

GBE/SVC/SALES-HQ/207-2106

D.O.A.

Workshop

21/06/2022 DHOM120064922200

Policy No. Claim Type

OD CLAIM - UNITED OVERSEAS INSURANCE

8 TUAS AVE 18

	L	A	В	0	U	R	C	Н	A	R	G	E	S
--	---	---	---	---	---	---	---	---	---	---	---	---	---

TO REMOVE AND REFIX FRONT 1 WINDSCREEN 2

TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC

3

FAULTS, TO CONDUCT DIAGNOSTICS CHECK REFIX AIRCON SYSTEM AND TOP UP 4

5

TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC

6 7

TO REMOVE AND INSTALL MOBILEYE TO REMOVE AND TO REMOVE AND REFIX FRONT DASHBOARD

TO CHECK FOR AND RECTIFY WIRING

GAS. TO CHECK FUNCTION

120 150.00 27004000.00 150 180.00 600? 700.00 1900 2000.00

LABOUR TOTAL:

8,080.00

SUB-TOTAL:

20,034.37

GST @ 7% for \$ 20,034.37

1,402.41

GRAND TOTAL (S\$):

21,436.78

LKK Auto Consultants

the Repairer of the following:

- · To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:











Industrial Vehicles. Financial Services. 41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676 Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500 Website: www.goldbell.com.sg

Co Reg No 198003963G

Page

3 / 3

ESTIMATE

Date

: 23/06/2022

To

UNITED OVERSEAS INSURANCE

LIMITED

Attn.

Office / Mobile

Email Address

From

GOLDBELL ENGINEERING PTE LTD CATHERINECHONGKL

Attn. Office / Mobile :

Email / Fax No. : CatherineChongKL@goldbell.com.sg

Reg No Model

: YQ5960K

: FEA01BR2SDEP CBU MT

Chassis No

: FFA01BA35337

Engine No

4P10E22602

Quotation No.

: 158957

Ref. No. D.O.A.

: GBE/SVC/SALES-HQ/207-2106

Policy No.

: 21/06/2022 : DHOM120064922200

Claim Type

: OD CLAIM - UNITED **OVERSEAS INSURANCE**

Workshop

: 8 TUAS AVE 18

PREPARED BY: CATHERINECHONGKL

SURVEYOR: MOBILE NO:

90010068

OFFICE FAX NO:

EMAIL ADDRESS : rasil a IKK auto con

EXCESS AMOUNT : _

REPAIR TYPE :

PART-BY-PART YLUMPSUM

AUTHORISATION:

AUTHORISED / NOT AUTHORISED

RE-SURVEY:

BEFORE PAINT DAFTER PAINT

NO. OF DAYS :

REMARKS :

LKK Auto Consultants hence notify

the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:









SINGAPORE ACCIDENT STATEMENT

MPORTANT NOTICE

[H31014. 1 (EE) OUI EUEZ 19:23 (SG [))

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will be insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving

and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 22/06/2022 19:23 (SGT) **Date of Accident** 21/06/2022 08:30 (SGT) Exact Location of Accident BKE, Singapore Additional Location Information

Country/State of Loss

Singapore

DETAILS OF OWN VEHICLE

YQ5960K Vehicle Registration Number

INSURED/POLICYHOLDER

Is company? TUNGSAN FOOD INDUSTRIES PTE LTD Name Of Registered Owner Company Reg No 1XXXXX472E SALES@TUNGSANFOOD.COM Fmail Address (Phone) +65-62576897 Mobile Phone No

Alternative Phone No

(Office) +65-62576897

VEHICLE PARTICULARS

Manufacturer Mitsubishi Canter Model Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to

vour vehicle? Vehicle Category

Transmission

Manual 2998

INSURANCE COMPANY

Name of Insurance Company Type of Coverage

Fleet Policy Policy Number

Cover Note Number

United Overseas Insurance Ltd

Comprehensive

Employment

Commercial vehicle

Yes

DHOM120064922200

DRIVER

Name of Driver Passport No/FIN

LAI HUEY SIANG GXXXXX781M

occupation 06/01/1978 Date Of Driving Pass Outdoor **Driving** experience 15/03/2016 Gender 6 YEARS AND 3 MONTHS Mobile Number Alt. Phone Number (Phone) +65-93628087 **Email Address** Address SALES@TUNGSANFOOD.COM Address complement BLK 428 WOODLANDS ST 41 Postcode Is the driver the policyholder? 730428 If No, Relationship of the Driver with the Insured No Does Driver Own Other Vehicles? **Employee** Vehicle Registration Number of Other Vehicle Owned by Driver No Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 21/6/22 AT AROUND 0830 HRS, I WAS DRIVING ALONG BKE. THE TRAFFIC WAS HEAVY AND MOVING SLOWLY. AS I WAS MOVING STRAIGHT BEHIND VEHICLE B (XE 7002 M), SUDDENLY VEHICLE B START TO JAM BRAKE. ACCORDING TO VEHICLE B DRIVER, THERE WAS A CAR WHO SUDDENLY WENT IN FRONT OF HIS VEHICLE, HENCE THE REASON HE HAVE TO BRAKE. I MANAGE TO BRAKE MY VEHICLE BUT I STILL HIT ONTO VEHICLE B REAR. THERE IS NO DAMAGE TO VEHICLE B. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No Was there any audio recorded? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number Vehicle Manufacturer XE7002M Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Name of Driver Commercial vehicle

/	
tac Number	
Address	
Address complement	
Postcode	
	<u>-</u>
Nature Of Damage	·
Details of property damaged in accident	
No. Of Passenger (Including Driver)	
es (moduling Diliver)	

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willul misrepresentation or withholding of material facts may allow insurance companies to regudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance Companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurence Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer , my w orkshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers law yers flaw firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect.
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or G/A to their third party service providers or agents (including their law your SPT fand) which may be sited outside of Singapore, for one or more of the above Purposes.

 TUNGSAN FOOD INDUSTRIES.

唐山食品工业私人有限公司 Singapore 758235 Tel: 6257 6697 (10 lines) Fax: 6257 8634 56 Sengko Driy

57 6897 (10 mgsanfood.com

Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personne!

Sketch Plan

VOL A: Y05960K

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle Vehicle Owner Particulars

Vehicle Owner Particulars Owner ID Type:				
Sent Small production of the State of the St	Company			
Owner ID: Vehicle Details	472E			
Vehicle No.:	YQ5960K			
Vehicle to be Exported:	No			
Intended Deregistration Date:	23 Jun 2022			
Vehicle Make:	MITSUBISHI			
Vehicle Model:	CANTER FEA01BR2SDEP (CBU)			
Primary Colour:	White			
Manufacturing Year:	2021			
Engine No.:	4P10E22602			
Chassis No.:	FEA01BA35337			
Maximum Power Output:	12			
Open Market Value:	\$31,696.00			
Original Registration Date:	15 Mar 2022			
First Registration Date:	15 Mar 2022			
Transfer Count:	0			
Actual ARF Paid: Intended PARF Rebate Details	\$1,585.00			
PARF Eligibility:	No			
PARF Eligibility Expiry Date:	•			
PARF Rebate Amount: Intended COE Rebate Details	\$0.00			
COE Expiry Date:	14 Mar 2032			
COE Category:	C - Goods Vehicle & Bus			
COE Period(Years):	10			
PQP Paid:	\$43,213.00			
COE Rebate Amount:	\$42,009.00			
Total Rebate Amount:	\$42,009.00			

Mitsubishi Fuso Canter FEA01

Overview

Curb Weight

2,500 kg

Financial Accessories

Similar

Research

Photos

Map





Lifespan 🐡 Price \$93,000 21-Apr-2041 Depreciation ... \$10,540 /yr Reg Date 22-Apr-2021 View models with similar depre (8yrs 9mths 25days COE left) Mileage 7,000 km (5.9k /yr) Manufactured: 2021 Road Tax N.A. Transmission Auto \$23,295 as of today (change) Dereg Value Fuel Type Diesel COE \$26,406 OMV \$34,271 Engine Cap 2,998 cc ARF 🕧 \$1,714

No. of Owners