



Service Requests

Messages

Claims



## Service Request Details

Claim

S2M03ZM0

Reference

CS3/ASM22006017/Rcy3m4

Loss Date

24 April 2022

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

27 Apr 2022 5:01:38 PM

Request Date

24 June 2022

## Actions

## Next Step

Wait for: Approve invoice

## Vehicle Information

Incident Vehicle Registration #

FBS4503R

Make

TPVD Yamaha

Model

Fz1-s

## Service Address

,,,

## Primary Contact/Insured

Due Date

COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE, 575717, Singapore  
65551188

Services

Pre-Repair Survey

### Claim Handler

OH Vale

vale.oh@axa.com.sg

Additional Instructions

Messages 2

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

**+** Upload Documents**Already Attached**

NAME

 ASM-LKKInvoice-AC2204040.pdf.pdf

TYPE

Email Sent

SUBTYPE

Surveyor/ Assessor expense

AUTHOR

LKK AUTO CONSULTANTS PTE LTD (TP)

DATE uploaded

1 July 2022

---

NAME	 LKKPreRepairInspection.pdf.pdf
TYPE	Reports & Statement
SUBTYPE	Survey Report
AUTHOR	LKK AUTO CONSULTANTS PTE LTD (TP)
DATE uploaded	1 July 2022

---

NAME	 LKKPhoto.pdf.pdf
TYPE	Evidence
SUBTYPE	Photos
AUTHOR	LKK AUTO CONSULTANTS PTE LTD (TP)
DATE uploaded	1 July 2022

---

NAME	 FBS 4503R_IA.pdf.pdf
TYPE	Reports & Statement
SUBTYPE	Others
AUTHOR	LKK AUTO CONSULTANTS PTE LTD (TP)
DATE uploaded	28 June 2022

---

NAME	 PRI TP PDF.pdf.pdf
TYPE	Legal
SUBTYPE	Others
AUTHOR	KUMAR Shailendra
DATE uploaded	23 June 2022

NAME	 PRI EMAIL FROM SOLICITOR.msg.msg
TYPE	Legal
SUBTYPE	Others
AUTHOR	KUMAR Shailendra
DATE uploaded	23 June 2022

---

NAME	 SHC3193X INSD GIA.pdf.pdf
TYPE	Reports & Statement
SUBTYPE	GIA Report
AUTHOR	KALE Nagesh
DATE uploaded	27 April 2022

---