ASS. RECABY: STENC	ASSIGNMENT.
	Cre 00 111 00 13/10
From: Date:	Type: M.Cyclo / Bus / Van / Lorry / Taxi / Prime Mover /
	Truck / Traller or
OD (TP) WS ITP RES I OD RES I EVA I INV I MV	Make: RMW X) c.c 1499
To Inspect Vehicle No:	Colour Whyle AC: Insured 18td 1 NI 1 NA
et Workshop m/s	7001
of	Sp.Reading (2 / 8)(5 T/Radio: Insured / Sto / Ri / RA
Insured:	CNO: WRATG120X0397624.
Policy No.	Gen. Cond: Good / Fair / Poor / Burnt
Claims No	Steering: Inforder / Jammed / Leaked / Burnt or
	Brake: Ingrag / Jammed / Leaked / Burnit or
(Client's Record)	
Make of Veh:	Modi: NII / STRIP / STD A/RIM or Tyre Size: F: 225/50R)8
	Tyre Size: F: 1775 30776
(Policy Condition) Remark The yeb had commenced its N/S	
Remark: The veh had commenced its . N/S repair at the time of inspection.	TOYO I YOKO Or .
\	Fron! Rear
Bal. or Market Value: IDAC Arcident Rood: Consistent?: Yes or No	R/Bal. L
IDAO Notice III A III	L/Bal / mm
GM / FN Cook	-0-10100 DOI 111/6/11/
Est Repairs: days Res.: Yes or No	- De Contrara Maria
Lum Sum: % · 3 Val.: Yes or No	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA REV REP. 24 HRS	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date/Time Action / Instruction	
MV-139 K	
	,
Osle/Time, File Pass to? : Prell. Report	Days Of Repair:
/i) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2)	Add Fee: Site Insp (\$)_s+Rs_si
	: Interview (\$) Photos
Report Formal :	:Tech, Invs (\$) Others
Lump Sun / I.B.f: (\$.) Weel:end (.)
	· TOTAL

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559N GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)



303. Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773 315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSales) 64796624 (Motorrad)

Steve (LKK) 29/6/22, 2-07 m r

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.

b1 62243

2243

Page No. : 1 of 6

Date Estimated Prepared By

: 22/06/2022

: Foong Shiuh Jye

- ESTIMATE REPAIR FOR -

SIM SHEN HENG, EUGENE 120 BEDOK NORTH ST 2

#13-180

- ACCOUNT - 40000 Cash Sales - Service

Singapore

SINGAPORE 460120

REGN. NO.

CHASSIS NO.

DESCRIPTION

REGN. DATE

MODEL

MILEAGE

SKF8811L

WBAJG120X03G77624

28/03/2019

X1 sDrive18i

56514

DESCRIPTION VALUE To replace bumper rear panel, boot lid, tail end panel, trunk floor, trunk 9,350.00 1100 830 X2 floor left and right, and repair both rear side panels 1972 To spray paint bumper rear panel, boot lid, tail end panel, trunk floor, 6,748.00 trunk floor left and right, rear both side panel 118.00 To carry out body cavity preservation. 112 (Per panel). 9 To carry out body cavity preservation. 531.00 (For cut panel). To replace rear windscreen glass. 574.00 To conduct water leak tests. 75.00 To supply and install rear windscreen solar film. (Check the Mice) 531.00 To vacuum glass debris 75.00 (frame only) 165.00 To supply rear emboss number plate. (Special type). To replace rear exhaust silencer including alignment 531.00 system and conduct check for leak. To check electrical wiring system and lighting at the 177.00 rear section for proper function. Sundries. 150.00



19,025.00

VALUE

Total Labour 1:

PRIC

QTY

Performance Motors Limited
A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020061-x
Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

280, Kampong Arang Road East Coast Centre Bingapore 438180 Fax. 63449773

115, Alexandra Road Sime Darby Business Centre Singapore 15994 Fax. 64796601 (AfterSales) 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X E S T I M A T E

istimate No.

pate Estimated

b1 62243

prepared By

: 22/06/2022

Page No.

Page No. : 2 of 6

prepared by

: Foong Shiuh Jye

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE 56514

SKF8811L

WBAJG120X03G77624

28/03/2019

X1 sDrive18i

DESCRIPTION QTY PRIC VALUE BOOTLID 1,298.95 1,298.95 TRUNK FLOOR 452.40 452.40 INTERIOR TAIL TRIM X 306.50 306.50 TAIL PANEL 420.70 420.70 LH TRUNK FLOOR 362.45 362.45 RH TRUNK FLOOR X 362.45 362.45 REAR LH BUMPER MOUNT 166.90 166.90 REAR RH BUMPER MOUNT 166.90 166.90 RR BUMPER CARRIER 523.75 523.75 MOUNTING SMART OPENER 47.00 47.00 REAR TRIM UNDERRIDE PROTECTION (X L (5/k-) / (R) 151.10 151.10 RR BUMPER LH CORNER MOUNTING 147.50 147.50 RR BUMPER RH CORNER MOUNTING 147.50 147.50 REAR BUMPER PANEL PRIMED 907.80 907.80 REAR BUMPER MIDDLE TRIM PANEL (PDC) (CIME) / CRU 266.90 266.90 REAR BUMPER TRIM BOTTOM (LINES) (150) / CR4 238.10 238.10 EMBLEM GROMMET - na 0.95 1.90 BMW PLAQUE WITH ADHESIVE FILM / 1/10C 72.85 72.85 **LETTERING S DRIVE 18I** 98.35 98.35 LETTERING X1 / MC 65.60 65.60 STRIKER BOOT LID 60.95 60.95 LOCK TRUNK LID X 230.30 230.30 X SOFT CLOSE AUTOMATIC 624.45 624.45 BOOT LID/TAILGATE PUSH BOTTON ICAM 42.35 42.35 LH SPRING SUPPORT 176.20 176.20 SPINDLE DRIVE 2 377.35 754.70 REAR BUMPER TOWING EYE COVER X 37.70 37.70 REAR WINDOW (ESG) / BR 815.55 815.55 THERMAL PROTECTION LUGGAGE COMP. FL 156.80 156.80 LOADING SILL COVER X 191.10 191.10 TRUNK FLOOR 579.40 579.40 LOWER TAIL LID TRIM PANEL (SCHWARZ) / UPPER TRUNK LID TRIM PANEL (EVEREST ? 167.95 167.95 42.10 42.10 LH TRUNK LID PANEL TRIM (EVERESTGRA / [M] 32.15 32.15 RH TRUNK LID PANEL TRIM (EVERESTGRA / € 32.15 32.15 TRUNK LID SPOILER PRIMED 757.40 757.40 AEROBLADE (SCHWARZ) X 558.15 558.15 REAR LH LIGHT IN TRUNK LID / (VI) 270.35 270.35 REAR RH LIGHT IN TRUNK LID X 277.10 277.10 REAR LH LIGHT IN THE SIDE PANEL 405.85 405.85 REAR RH LIGHT IN THE SIDE PANEL X 405.85 405.85 SET ADHESIVE PADS FOR ACE 2.0 / n/k 37.35 37.35 **BMW ADVANCED CAR EYE 2.0** 892.25 892.25 (DG) CLEANER R1 (100ML) / mis 26.15 26.15 (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) / /K 131.55 263.10 (DG/SL)ADHESIVE PRIMER VP 206 (30ML / NG 27.85 27.85 14,070.85 Total Parts

erformance Motors Limited

Sime Darby Motors Company to. Reg. No. 197401559N GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

280, Rampong Arang Road Hast Coast Centre Singapore 438180 Fax. 63449773

115, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSal 64796624 (Motorrad (AfterSales)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

stimate No.

: b1 62243

Date Estimated

: 22/06/2022

prepared By

: Foong Shiuh Jye

Page No. : 3 of 6

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SKF8811L

WBAJG120X03G77624

28/03/2019

X1 sDrive18i

56514

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1 19,025.00 : Parts 14,070.85 : Labour 2 0.00 Excess 0.00 Total GST @ 7% 2,316.71 Grand Total 35,412.56

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate 3, Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material racta may allow policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 22/06/2022 11:33 (SGT) Date of Accident Exact Location of Accident 21/06/2022 10:30 (SGT) Singapore Additional Location Information **CTE EXIT 15A** Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKF8811L

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner SIM SHEN HENG, EUGENE NRIC No SXXXX520Z Email Address CD.EUGENE@GMAIL.COM Mobile Phone No (Phone) +65-91287979 Alternative Phone No (Home) +--

VEHICLE PARTICULARS


BMW Model and the second s **X1** Variant Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Private car Transmission Auto CC 1499

INSURANCE COMPANY

Name of Insurance Company Liberty Insurance Pte Ltd Type of Coverage Comprehensive Fleet Policy Policy Number SD20V01671/VPC2/R01 Cover Note Number

DRIVER

Name of Driver SIM SHEN HENG, EUGENE SXXXX520Z



Page 1 of 27



te Of Birth 11/11/1968 ecupation rate Of Driving Pass Indoor 18/11/1989 **Driving** experience 32 YEARS AND 7 MONTHS Gender Mobile Number Male (Phone) +65-91287979 Alt. Phone Number (Home) +--**Email Address** CD.EUGENE@GMAIL.COM Address **BLOCK 120 BEDOK NORTH STREET 2** Address complement #13-180 Postcode 460120 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver No Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT SEE ATTACHED SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No Was there any audio recorded? No **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number **GBE8767T** Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Commercial vehicle Name of Driver YEO GEK HWA NRIC No SXXXX360E Contact Number (Phone) +65-90908849 Address

BLOCK 515A TAMPINES CENTRAL 7

Accident report SP01226M0001

Page 2 of 27

Address complement

Postcode
Postcode
Insurance Company Name
Solution
Postails of property damaged in accident
No. Of Passenger (Including Driver)

#07-08
#07-08
#07-08
FRONT



....:

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

GIARMC SketchPlanForm_V3

CS CamScanner

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	
At CTE exit 15A heavy traffic in fort, I followed to slow down	
At CTE exit 15A heavy traffic in frost, I followed to slow down and stop, sublinly heard the bang from the near, realising GBE87677	
knocked into my uchicle SKF 88112.	
Suso .	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

GIARMC SketchPlanForm_V3