

(08/11/13) wef
ASS. REC. BY: *[Signature]*

REF:

CS/SCD 22006043/Rog3


6184

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *SY 40C*
at Workshop m/s *Vin's motor*
of *160 SENMARA SL #08-09*
Insured: *SCD*
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: *70K*
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: *2* days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: *SY 40C* Yr Regn: *2017 / Jan*
Type: *M.Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: *VOLKSWAGEN SP VAN 1.4 HL* *5/12* *139K*
Colour: *Brown* A/C: Insured / Std / NI / NA
Sp. Reading: *67171* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *WUW222AU76W595098*
Gen. Cond: Good / *Fair* / Poor / Burnt
Steering: *Inorder* / Jammed / Leaked / Burnt or
Brake: *Inorder* / Jammed / Leaked / Burnt or
Modi: Nil / *S/Rim* / STD A/Rim or
Tyre Size: F: *225/40R18*
R: *225/40R18*

BS / DUN / EXNOVA / *GY* / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front Rear
R/Bal. *6* mm R/Bal. *6* mm
L/Bal. *6* mm L/Bal. *6* mm
D.O.A. *13/06/22* D.O.I. *27/06/22*
Survey held at *Vin's motor*

Des. of Damages *Fr* / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 28K

Rasul finalised final fig \$971.50, 2 days. (Red \$2521.10, 72%)

Date/Time, File Pass to?

☐

: Prell. Report

1) 15/07 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: *2*

Resurvey No. of Trip: *2*

Survey Fee:

Transportation:

) *S + RS*, *SI*

) Photos

) Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL

Report Format : *TP*

~~Lump Sum~~ / I.B.I: (\$ *971.50*)

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : Singapore Civil Defence Force
91 Ubi Avenue 4
Singapore 408827

Claim Details

Case Ref. No. : TP/062022/5496
Date : 27-06-2022
Accident Date : 13-06-2022

Vehicle Details

Make & Model : Volkswagen SPORTSVAN 1.4
HIGHLINE AM14HZ
Chassis No : WVWZZZAUZGW599098
Registration No : SY40C

Third Party Vehicle Details

Registration No : GBF8696J

S/N	Description	Qty	Amount (\$\$)
1	FRONT BUMPER <i>repair</i>	1.00	\$890.00
2	FRONT BUMPER PARKING SENSOR ?	1.00	\$165.00
3	FRONT BUMPER SPONGE X	1.00	\$69.00
4	FRONT BUMPER REINFORCEMENT X	1.00	\$520.00
5	FRONT BUMPER CLIPS X	10.00	\$700.00
6	FRONT GRILLE ASSY <i>cm</i>	1.00	\$470.00

\$2,814.00

Discount: -10%

(\$281.40)

\$2,532.60

7 TO REPAIR DAMAGES

1.00

~~\$480.00~~ *200*

8 TO SPRAY PAINTING

1.00

~~\$480.00~~ *200*

Subtotal w/o GST:

\$3,492.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.

Rand
Hp 90010068
2 days
P/P
27/06/22 015K5
Reg after paint
new grille photo

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	15/06/2022 00:35 (SGT)
Date of Accident	13/06/2022 12:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONG QUEENSWAY
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SY40C
-----------------------------	-------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	HENG JUN LI MELVIN
NRIC No	SXXXX618H
Email Address	melvinheng@gmail.com
Mobile Phone No	(Phone) +65-90909964
Alternative Phone No	+65-97697612

VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	SPORTSVAN
Variant	1.4
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1395

INSURANCE COMPANY

Name of Insurance Company	Singapore Life Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	11043059
Cover Note Number	-

DRIVER

Name of Driver	ABEL NG YONG BOON
NRIC No	SXXXX315Z

Date Of Birth	24/05/1984
Occupation	Indoor
Date Of Driving Pass	20/06/2006
Driving experience	16 YEARS
Gender	Male
Mobile Number	(Phone) +65-97697612
Alt. Phone Number	-
Email Address	yongboonabel@gmail.com
Address	9 FARRER DRIVE
Address complement	#03-03
Postcode	259279
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Relative
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit by fallen tree / Other objects
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	4
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	Passenger 1
Gender	Female

PASSENGER 2

Name	Passenger 2
Gender	Male

PASSENGER 3

Name	Passenger 3
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

MY FAMILY AND I WERE TRAVELING ON THE FARRER UNDERPASS FROM QUEENSWAY TOWARDS FARRER ROAD AND HAVE JUST ENCOUNTERED A BOOT THAT WAS FLUNG OUT FROM A RHINO (GBF 8696 J) AND STUCK THE CAR. AS SUCH, THE CAR SENSOR IS MALFUNCTIONING WITH A SMALL COVER FELL OFF AND A CRACK TO THE VEHICLE PLATE NUMBER HOLDER.

I HAVE A VIDEO AND PICTURE EXCEEDING 2 MB.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? Yes
Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBF8696J
Vehicle Manufacturer Isuzu
Vehicle Model TFS86JDR(A)
Vehicle Variant -
Vehicle Colour -
Vehicle Category Government
Name of Driver -
Contact Number -
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident Hit by boots fallen from third party truck
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

**VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMED SAIFULLAH S/O SYED MASOOD**

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

14 June 2022

Queensway



Boots



Vehicle A SY40C

Vehicle B GBF8696J



VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMED SAIFULLAH S/O SYED NASOOR

Reporter's Signature
Date & Time

Driver's Signature
(If driver is not the owner, NO/OK)
Date & Time

Reporting Officer's Signature
Name
ARC/IN/NO

SKETCH PLAN

REFER TO ATTACHED ACCIDENT DIAGRAM

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PLEASE REFER TO POLICE REPORT T/20220613/7067

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

14 June 2022

**VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER**

MOHAMED SAIFULLAH S/O SYED MASOOD

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GIARMC Sketch/Report V3



SINGAPORE POLICE FORCE



T/20220613/7067

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20220613/7067

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/06/2022 21:35		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: ABEL NG YONG BOON			Address: 9 FARRER DRIVE #03-03 SINGAPORE 259279		
ID Type / ID No.: NRIC NO / S8415315Z			Contact No.: Home/Office: Mobile: 97697612		
Nationality: SINGAPORE CITIZEN			Email: yongboonabel@gmail.com		
Sex: Male	Age: 38	Date of Birth: 24/05/1984	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Technology Risk Officer			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 13/06/2022 12:30	Type of Location: Farrer Underpass
Location: QUEENSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume: Light	
Type of Collision: No collision			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of
SY40C	Car					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20220613/7067

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20220613/7067

CONTINUATION OF REPORT

Driver				
Name	ABEL NG YONG BOON		ID No.	S8415315Z
Related Vehicle	SY40C (Car)		Contact No.	97697612
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL	
No. of Days granted Medical Leave	NIL	Degree of	NIL	

Brief Details.

My family and I were traveling on the Farrer Underpass from Queensway towards Farrer Road and have just encountered a boot that was flung out from a Rhino (GBF 8696 J) and struck the car. As such, the car sensor is malfunctioning with a small cover fell off and a crack to the vehicle plate number holder.

I have a video and picture exceeding 2 MB.



**SINGAPORE
POLICE FORCE**



T/20220613/7067

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20220613/7067

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
TAN JEOK LENG
Contact No.: 65476151

Signature Of Informant:
The identity of the person making this report has
been authenticated by Singpass. No signature is
required.

Date/Time:
13/06/2022 21:35

Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	618H
Vehicle Details	
Vehicle No.:	SY40C
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Jun 2022
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SPORTSVAN 1.4 HIGHLINE AM14HZ
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	CZC550958
Chassis No.:	WWWZZZAUZGW599098
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$27,472.00
Original Registration Date:	25 Jan 2017
First Registration Date:	25 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$25,461.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jan 2027
PARF Rebate Amount:	\$17,822.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,889.00
COE Rebate Amount:	\$23,283.00
Total Rebate Amount:	\$41,105.00

The information contained herein is correct as at 24 Jun 2022

OK

Volkswagen Sportsvan 1.4A TSI Comfortline

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Das WeltAuto.

Used cars you can trust. Guaranteed.

Price

\$75,988

Depreciation ⓘ

\$13,450 /yr

[View models with similar depre](#)

Reg Date

23-Jun-2017

(4yrs 11mths 25days COE left)

Mileage ⓘ

90,000 km (17.9k /yr)

Manufactured ⓘ

2015

Road Tax ⓘ

\$624 /yr

Transmission

Auto

Dereg Value ⓘ

\$33,853 as of today (change)

OMV ⓘ

\$22,052

COE ⓘ

\$42,801

ARF ⓘ

\$17,873

Engine Cap

1,395 cc

Power

92.0 kW (123 bhp)

Curb Weight ⓘ

1,383 kg

No. of Owners ⓘ

1