

ASS. REC. BY: Taufik

REF:

CS/7M/22006051/7933

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: Juman Vehicle: IN / OUT

Veh No: SH6136K Yr Regn: 2019, May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prim C.C. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 311466 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 5TDK133F4003080012

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 2 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wentube

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. \_\_\_\_\_ mm

D.O.A. \_\_\_\_\_ D.O.I. 24/6/22

Survey held at Comfort byang

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Taufikh re-finalised LS \$2600, 2 days. (Red \$3348.44, 56%)

Date/Time, File Pass to?  : Preli. Report  
1) 07/09 Typist  : Final Report

Date/Time, File Return to?  
2) \_\_\_\_\_

Report Format: MER-TP  
Lump Sum (L.S.): 2600

Days Of Repair: 2  
Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech. Invs (\$)  
 : Weekend (\$)

Survey Fee:	
Transportation:	
S + RS	SI
Photos	
Others	
TOTAL	

## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ)  
**CTPL**

Singapore

*Jumani Bin Masudin*

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	24/06/2022
Vehicle Reg. No.:	<b>SH6136K</b>	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Vehicle Reg. Date:	15/05/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2C16166	Chassis No:	JTDKB3FU003080512
Odometer:	0 KM		
Paint Type:		Nett Item Discount:	20.00 %
List Item Discount:	20.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	4,247.44
Miscellaneous Items	11.00
Labour	1,690.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>5,948.44</b>
<b>+ GST 7.00% (S\$)</b>	<b>416.39</b>
<b>Nett Amount (S\$)</b>	<b>6,364.83</b>

**This claim is handled by: JUMANI BIN MASUDIN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 24 Jun 2022)**Parts:** 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SH6136K/24/06/2022 14:22**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT DOOR LH	20.00	0.00	<i>bt</i> *2,164.00 FL
2	1		*REAR DOOR LH	20.00	0.00	<i>bt</i> *1,258.30 FL
3	1		*SIDE MIRROR LH ASSY	20.00	0.00	<i>x</i> *1,390.10 FL
4	1		*SIDE MIRROR COVER LH	20.00	0.00	<i>fx</i> *141.90 FL
5	1		*FRT DOOR COMFORT LOGO	20.00	0.00	<i>net</i> *75.00 FN
6	1		*REAR DOOR APPS LOGO	20.00	0.00	<i>net</i> *80.00 FN
7	1		*ADVERTISEMENT LOGO FRT DOOR	20.00	0.00	<i>cut</i> *100.00 FN
8	1		*ADVERTISEMENT LOGO REAR DOOR	20.00	0.00	<i>cut</i> *100.00 FN

F=Franchise part. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (S\$)</b>	<b>5,309.30</b>
- List Item Discount on L Items (S\$)	990.86
- Nett Item Discount on N Items (S\$)	71.00
<b>Total Parts (S\$)</b>	<b>4,247.44</b>

ComfortDelGro Engineering Pte Ltd/SH6136K/24/06/2022 14:22. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

### Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>

### Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	850 800.00
2	SPRAYPAINT	New	500 600.00
3	CHECK WIRING	New	x 50.00
4	TRANSFER DOOR PARTS	New	120. 240.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,690.00</b>

ComfortDelGro Engineering Pte Ltd/SH6136K/24/06/2022 14:22. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

*Tan Jhu 97495749  
 'up' 24/6/22 @ 3pm  
 LLS heavy after repair  
 tan jhu @ 1 hr auto-car  
 3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

am: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order:


JC NO305520845

OMER  S COMFORT TRANSPORTATION PTE LTD OMER NO. 7010045 ESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P)	REGN NO.: <b>SH 6136K</b>	MILEAGE
	MAKE: <b>TOYOTA</b>	FUEL E.....1/2.....F
	MODEL <b>PRIUS HYBRID(G4)24</b>	DATE/TIME IN <b>06.2022 10:55</b>
	YR OF MANU. <b>15.05.2019</b>	TARGET DATE
	CHASSIS CODE <b>JTDKB3FU003080512</b>	COMPLETION DATE/TIME:

Accident Date: 24.06.2022  
 NATURE: 3P 24.06.22/C

JOB DESCRIPTION

NO LABOR CODE DESCRIPTION



REMOVED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Identification Slip

Exit Pass

Vehicle No.: **SH 6136K**

**JU TOKIO**

Vehicle No.:

**SH 6136K**

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard