



Your Ref: 22.29466

Date: 24th Aug 2022

Our Ref: CS3/ASM21008620/Gqy3e2-1

M/s Axa Insurance Pte Ltd

C/o Seah Ong & Partners LLP

36 Robinson Road #12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKN 5325B

INSURED VEHICLE: SHA 8044X

ACCIDENT DATE: 15/08/2021

We thank you for your instruction on 20/06/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKN 5325B from M/s Aeon Auto Consultants LLP.
- b) Singapore Accident Statement of Vehicles SKN 5325B and SHA 8044X.
- c) Final Repair Bill of SKN 5325B from M/s Horsepower Workshop Pte Ltd.
- d) Colour damaged vehicle photographs of SKN 5325B.

Pre-Repair Inspection Date: 18/08/2021 at M/s Horsepower Workshop Pte Ltd, 1 Kaki Bukit Avenue 6 #01-96 Autobay@Kaki Bukit, Singapore 417883.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKN 5325B
Make & Model	: B.M.W. 316I 1.6 AT D/AB 4DR ABS HID
Year of Registration	: 2014
Chassis Number	: WBA3A16070NS37270
Engine Capacity	: 1598 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.