

PRS ASSIGNMENT

14 Jan 2016

From: CS3/LPC22001117/Gtf3 Date:

Veh No: SKZ 2223T Yr Regn: - /

Estimated Cost:

Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD: TP / S / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make: HONDA VEZEL c.c - 1496

at Workshop m/s: TT Motorsport

Colour: BLUE A/C: Insured / Std / NI / NA

of

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No: -RU11105730

Claims No:

Gen. Cond: Good Fair / Poor / Burnt

Sum Insured: Excess:

Steering: Inorder Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil S/Rim STD A/Rim or

(Policy Condition)

Tyre Size: F: 215/55ZR17 R: 215/55ZR17

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	N/S	O/S
<input type="checkbox"/>		

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or HABLEAD

Bal. or Market Value: \$

Front Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal. 6 mm R/Bal. 6 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 6 mm L/Bal. 6 mm

Est. Repairs: 10 days Res.: Yes or No

D.O.A. D.O.I. 07-02-2022

Lum Sum: 20 % 3 Val.: Yes or No

Survey held at W/S 5PM

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted: Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$8000 - \$12000
	No GIA provided SUBMIT PRS REPORT

Date/Time, File Pass to? : Preli. Report

Days Of Repair: 10

1) : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: : Site Insp (\$)

Survey Fee:	
Transportation:	
3 + RS. SI	
Photos	
Other:	
TOTAL	

: Interview (\$)

: Tech. Insp (\$)

: Wheel end (\$)

Report Filed:

Long Copy / MPB: