

ASS. REC. BY: Taufik

REF:

NSI/INC 22006060/Tvc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SJP 9734D

Policy No. _____

Claims No. MT/1175445-002


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Mg Loh

Veh No: SHD 3259K Yr Regn: 2016 June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai 140 c.c 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 566713 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHL641UMG 4091565

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wstake

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 6/6/2022 D.O.I. 7/6/22

Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TRINC SJP9734D
29/7/22	Taufikh informed LS \$2100 (Red 749.56, 26%)

Date/Time, File Pass to? : Prell. Report : Final Report

1) _____ Date/Time, File Return to? 2) 1/8/22-typist

Days Of Repair: 2 Resurvey No. of Trip: 2

Rep. Format: TP Lump Sum / L.B. (\$) \$2100

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)

Survey Fee:
Transportation:
\$ + RS. \$I
Photos
Others
TOTAL

COMFORT TRANSPORTATION PTE LTD
REPAIR ESTIMATE

Vehicle No. : ~~SHG 2064~~ SHD 3259K

Date: 07/06/2022

Make : HYUNDAI

Insurance: NTUC

Model : I-40

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			\$ 1,052.20
10	FRT BUMPER CLIPS			\$ 22.00
1	RADIATOR GRILLE			\$ 1,480.00
1	FRT BUMPER CENTRE GRILLE			\$ 114.00
	SUB TOTAL			\$ 2,668.20
	LESS 20%			\$ 533.64
	DISCOUNTED TOTAL			\$ 2,134.56
	FRT NUMBER PLATE WITH TRIM COVER			\$ 55.00
				\$ 55.00
	Labour Charge			
	CHL ALL LIGHTING			\$ 60.00
	PANEL BEATING			\$ 300.00
	SPRAY PAINTING CHARGE			\$ 300.00
	TOTAL LABOUR			\$ 660.00
	ESTIMATE TOTAL			\$ 2,849.56

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97445749
 WP' 7/6/22 C315p
 -2days
 4/5 Resum after repair
 Tanpin ekkantokun

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4254170

JC NO.305518767

STOMER
/MS COMFORT TRANSPORTATION PTE LTD
STOMER NO. 7010045
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

REGN NO: SHD3259K	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 06.06.2022 18:15
YR OF MANU 30.06.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU091565	COMPLETION DATE/TIME:


COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 06.06.2022
NATURE: 3P 06.06.2022

S/NO LABOR CODE

DESCRIPTION



CKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

medgement Slip

Exit Pass

No.: **SHD3259K** **YY**

Vehicle No.: **SHD3259K**

Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard