

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

NOTUC (L&S)

Date: 15.06.2022
Time: 15:34:55
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305519829
REGN NO : SHC7061S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 07.04.2016
DATE/TIME IN : 15.06.2022 12:35
ACCIDENT DATE : 14.06.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	553.00	20.00	442.40	de
0002 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10	22.00	20.00	17.60	nc
0003 04-01-0103-0907-G	BRKT ASSY-RR BUMPER SIDE	1	35.60	20.00	28.48	de

SUB-TOTAL : 488.48

JOB NATURE

0000 PB	PANEL BEATING	300.00	280
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	REMOVE/REFIX REVERSE SENSOR	50.00	30

SUB-TOTAL : 650.00

TOTAL : 1,138.48

MVA NAME & SIGNATURE
DATE:

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE:

Tamjin 94495749
wp 15/6/22 430
2 days
1/5 Remy after repair
tamjin ellahandran

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date/Time: 15.06.2022 15:35

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4290835

JC NO.305519829


CUSTOMER NAME: CITYCAB PTE LTD CUSTOMER NO: 7010070 ADDRESS: 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65551188 (O) (P)	REGN NO.: SHC7061S	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN 15.06.2022 12:35
	YR OF MANU. 07.04.2016	TARGET DATE
	CHASSIS CODE KMHLB41UMGU086739	COMPLETION DATE/TIME:
	DUNT CARD NO.	

JOB DESCRIPTION

Accident Date: 14.06.2022
TIME: 3P 14.06.22

/NO	LABOR CODE
00040	PB
00050	SP
00060	L

DESCRIPTION
 PANEL BEATING
 SPRAYPAINT CHARGE
 REMOVE/REFIX REVERSE SENSOR



KED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

All p

edgement Slip

This

Exit Pass

No.: **SHC7061S**

JU NTUC

Vehicle No.:

SHC7061S

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard