

TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE

#15-08 WESTGATE TOWER SINGAPORE 608531

TEL : 6849 8118

FAX:

ATTN: ACCOUNTS DEPT

YOUR REF NO : XD3275Z

CLAIM TYPE

: THIRD PARTY

TP INS. CO. : A

: AXA INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 20/06/2022 TP VEH REG NO : XD3275Z

ESTIMATE

NO : QUOT202206-000069(00)

DATE : 24/06/2022
POLICY NO : 999995580
VEH REG NO : SMQ3443S

MAKE/MODEL : MERCEDES BENZ GLA180

URBAN (R18 LED)

CHASSIS NO : WDC1569422J665702

ENGINE NO : 27091031918416 REG. DATE : 2019

Estimate Repair Cost to Vehicle No: SMQ3443S

	Description	Quantity	Unit Price	Amount
			<u>S\$</u>	<u>S\$</u>
	NET PRICE			
1	Rear bumper	1	1,230.00	1,230.00
2	Rear bumper side retainer RH	1	38.00	38.00
3	Rear bumper sensor	1	215.00	215.00
4	Rear bumper sensor seals	8	12.00	96.00
5	Rear bumper clips	15	9.00	135.00
6	Rear fender - RH	1	2,680.00	2,680.00
7	Rear sport rim - RH	1	950.00	950.00
8	Rear wheel arch garnish RH	1	260.00	260.00
9	Taillamp assy - RH	1	848.00	848.00
10	Taillamp lower bracket RH	1	73.00	73.00
11	Rear door - RH	1	2,205.00	2,205.00
12	Rear door weatherstrip - RH	1	328.00	328.00
13	Rear door trimboard rivets - RH	20	12.00	240.00
14	Rear door sticker RH	1	98.00	98.00
				9,396.00
			Less 10%	939.60
				8,456.40
	LABOUR			
	To transfer RH rear door interior mechanism & glass to new door	1	150.00	150.00
16	To remove and refit RH rear interior garnishes and trimboard to facilitate the repairs	1	280.00	280.00
17	To remove and refit rear bumper sensor	1	100.00	100.00
18	To check and rectify wiring system	1	80.00	80.00
19	To panel beat and straighten RH rear fender inner panel, RH rear chassis frame, to cut and weld RH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	1,500.00	1,500.00
20	To putty and spray paint on affected areas	1	1,500.00	1,500.00
21	To apply rust proofing on repaired and repalced panels	1	120.00	120.00
22	To computerise check wheel alignement	1	120.00	120.00
			_	3,850.00
				10



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE

#15-08 WESTGATE TOWER SINGAPORE 608531

TEL: 6849 8118

FAX:

ATTN: ACCOUNTS DEPT

YOUR REF NO

: XD3275Z

CLAIM TYPE

: THIRD PARTY

TP INS. CO.

: AXA INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 20/06/2022 TP VEH REG NO : XD3275Z

ESTIMATE

NO

: QUOT202206-000069(00)

DATE

: 24/06/2022

POLICY NO

: 999995580

VEH REG NO : SMQ3443S

MAKE/MODEL: MERCEDES BENZ GLA180

URBAN (R18 LED)

CHASSIS NO : WDC1569422J665702

ENGINE NO : 27091031918416

REG. DATE

: 2019

Estimate Repair Cost to Vehicle No: SMQ3443S

Description	Quantity	Unit Price	Amount	
		<u>S\$</u>	<u>S\$</u>	
		TOTAL	S\$ 12,306.40	
		ADD GST @ 7%	861.45	
		GRAND TOTAL	S\$ 13,167.85	

SINGAPORE DOLLAR THIRTEEN THOUSAND ONE HUNDRED SIXTY-SEVEN AND CENTS EIGHTY-FIVE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

TONGULGRANTO

TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

AXA INSURANCE SINGAPORE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 24 June 2022

Attn: MOTOR CLAIMS DEPT

Dear Sirs / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: SMQ3443S & XD3275Z ON 20/06/2022 @ 15:05 HRS ALONG KJE TPWARDS TUAS

We hereby authorized by our client **DAIMLER FLEET MANAGEMENT S'PORE PTE LTD**, the owner/driver of the above mentioned vehicle No.: **SMQ3443S**

We notice that the above accident was caused by your insured/driver negligent driving and/or management of motor vehicle No.: XD3275Z

Therefore we are instructed by our client to claim against you/your insured driver in connection with the above captioned accident involving our client's vehicle No.: **SMQ3443S** and vehicle No.: **XD3275Z** by your insured/driver at the material time. As a result, our client's vehicle was damaged and our client has been put to loss and expenses. Please assign your surveyor to inspect the above mentioned vehicle in the next 48hrs. Filling which, we will proceed to the repair of the vehicle. Details of claim will submitted to you in due course.

The vehicle is now garage at:

TONG LUCK AUTO PTE LTD

160 Sin Ming Drive

#07-01/06 Sin Ming Autocity

Singapore 575722 Tel: 6250 0088

Your kind attention to the matter would be much appreciated.

Yours faithfully,

TONG LUCK AUTO PTE LTD

SA0A226K000N / Ajax Mars Pte Ltd ENTRY DATE & TIME: 21/06/2022 23:49 (SGT) SUBMITTED BY: Susan VERSION: 1 (21/06/2022 23:49 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

21/06/2022 23:49 (SGT) 20/06/2022 15:05 (SGT) Singapore KJE towards Tuas Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SMQ3443S

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No

Email Address Mobile Phone No

Alternative Phone No

DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD

1XXXXXXX78Z

derrick.lee@mercedes-benz.com

(Phone) +65-81268670 (Office) +65-68498118

VEHICLE PARTICULARS

Manufacturer

Model Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category Transmission

CC

Mercedes Gla180

URBAN (R18 LED)

Private hire

No - Claiming third party

Private car Auto 1595

INSURANCE COMPANY

Name of Insurance Company Type of Coverage

Fleet Policy Policy Number Cover Note Number

AIG Asia Pacific Insurance Pte. Ltd.

Comprehensive

Yes

999995580

DRIVER

Name of Driver NRIC No

TAN SOON MENG SXXXX111F



Date Of Birth

Occupation

Date Of Driving Pass

Driving experience

Gender

Mobile Number

Alt. Phone Number

Email Address

Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions

Weather Conditions Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

I was driving on the extreme left lane along KJE towards Tuas when suddenly vehicle B swerve into my lane and collided with my car. My rear right was damaged. No injury involved

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Was there any audio recorded?

Yes

24/12/1980

20/03/2004

18 YEARS AND 3 MONTHS

Grandeur Park Residences, 1 Bedok South Avenue 3

(Phone) +65-90050868

topgon105@gmail.com

Indoor

Male

#11-19

465461

Side Swipe

Clear

Dry

Νo

No

Yes

1

Nο

No

No

Νo

No

Hirer

No

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model Vehicle Variant

venicle variant

Vehicle Colour

Vehicle Category Name of Driver

NRIC No

Contact Number

XD3275Z Man

Tgs

_

Commercial vehicle

WU JIAN

GXXXX546Q

-89420898



-
_
-
_
_
-

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

VERIFY BY AJAX MARS (ARC) REPORTING OFFICER MOHAMED SHARIL BIN SATAR

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

SKETCH PLAN #2



KETCH PLAN		
REFER TO ATTAC	CHED ACCIDENT DIAGRAM	
DESCRIBE CIRCUMSTANCES		
	to my lane and collided with i	towards Tuas when suddenly my car. My rear right was
, ,		
		w.
DECLARATION	ticulars are true in every respect.	
7 we deciate the foregoing part	(A)	VERIFY BY AJAX MARS (ARC) REPORTING OFFICER MOHAMED SHARIL BIN SATAR
Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No.: