

ASS. REC. BY:

REF: AIS/22008085/KgKenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Colou Vibeof 05-11Insured: 18417

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 2pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 26 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBE 8137L Yr Regn: 03, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: NIS NV350 c.c. 2488Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 23 8884 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNIM 22E 26 E 0006464

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim orTyre Size: F: 195R15X8

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 22/6/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Time, File Pass to?

☐ : Prell. Report☐ : Final Report

Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

rt Format :

Sum / I.B.I: (\$

COLOUR VIBE PTE. LTD.

176 Sin Ming Dr, #05-16 Sin Ming AutoCare, Singapore 575721

Company Registration No: 202203460Z

Email: business@colourvibe.sg

Contact: (+65) 94594918

Car Make & Model : Nissan NV350

Carplate : GBE 8137 L

Kenneth
96910663

NOT Notified
11/10/23
Morning After Rain
3 days

LIST ITEM			
DESCRIPTION	QUANTITY	PRICE	TOTAL
TAILGATE	1	\$ 2,101.40	\$ 2,101.40
TAILGATE OUTER CHROME MOULDING	1	\$ 370.90	\$ 370.90
TAILGATE INNER LOCK	1	\$ 183.90	\$ 183.90
TAILGATE WEATHERSTRIP	1	\$ 129.30	\$ 129.30
TAILGATE LOGO	1	\$ 62.50	\$ 62.50
TAILGATE "NV350" EMBLEM	1	\$ 89.00	\$ 89.00
TAILGATE "URVAN" EMBLEM	1	\$ 75.00	\$ 75.00
TAIL LAMP PANEL	2	\$ 324.80	\$ 649.60
REAR END PANEL	1	\$ 966.70	\$ 966.70
REAR END PANEL INNER MEMBER	1	\$ 588.50	\$ 588.50
REAR END PANEL INNER GARNISH	1	\$ 70.20	\$ 70.20
REAR BUMPER	1	\$ 899.70	\$ 899.70
REAR BUMPER BRACKETS	2	\$ 95.00	\$ 190.00
REAR BUMPER SIDE RETAINER	2	\$ 48.50	\$ 97.00
REAR BUMPER INNER SPONGE	1	\$ 88.90	\$ 88.90
REAR WINDSCREEN INNER SEAL	1	\$ 105.00	\$ 105.00
REAR STEP PANEL	1	\$ 192.60	\$ 192.60
REAR NUMBER PLATE LAMP	2	\$ 54.00	\$ 108.00

SPECIAL NETT ITEM			
DESCRIPTION	QUANTITY	PRICE	TOTAL
REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00
REAR TAILGATE "70KM/H" STICKER	1	\$ 18.00	\$ 18.00
REAR BUMPER CLIP (SET)	1	\$ 50.00	\$ 50.00
REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00
REAR REVERSE SENSOR	1	\$ 350.00	\$ 350.00
DECAL "6747 5028"	1	\$ 80.00	\$ 80.00
DECAL "8292 8821"	1	\$ 80.00	\$ 80.00

LABOUR CHARGE			
DESCRIPTION	QUANTITY	PRICE	TOTAL
TO REMOVE AND REFIX INNER GARNISH	1	\$ 150.00	\$ 150.00
TO REMOVE & REFIX REVERSE SENSOR	1	\$ 120.00	\$ 120.00
TO TRANSFER TAILGATE MECHANISM	1	\$ 80.00	\$ 80.00
TO REMOVE & REFIX REAR WINDSCREEN GLASS	1	\$ 200.00	\$ 200.00
TO APPLY UNDER COATING	1	\$ 150.00	\$ 150.00
PANEL BEATING, REMOVAL & REPLACEMENT ABOVE PARTS	1	\$ 1,500.00	\$ 1,500.00
TO RESPRAY PAINTING ON AFFECTED AREA	1	\$ 1,000.00	\$ 1,000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL