

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22006094/Rcy3e2	
	8 SHENTON WAY AXA TOWERSING		1	Date:	01/07/2022	
	ATTN: HO WINNIE		(	Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHD 3452T	Veh. Inspected		SLN 9334L	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S2M0452F	Excess (\$)		0.00	
	Assign From	HO WINNIE	Assign Date		27/06/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	B.M.W. M3 COUPE 4.0 SMT	c.c		3999	
	Engine No.	HIDDEN	Year of Reg.		2011	
	Chassis No.	WBSKG92050E698526	Colour		BLACK	
	Odometer	136626 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	265/35Z R19	MICHELIN		6 mm	
	L/H Front Tyre	265/35Z R19	MICHELIN		6 mm	
	R/H Rear Tyre	265/35Z R19	MICHELIN		6 mm	
	L/H Rear Tyre	265/35Z R19	MICHELIN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5. General Information						
	Accident Date	23/06/2022	Inspect Date / T	ime	28/06/2022 ( 02:15 PM )	
	Survey held at	JSSPRAYWERKS				
		5035 ANG MO KIO INDUSTRIAL PARK 2, #01-355, ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569538				
5a.	Sa. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/ASM22006094/Rcy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser