

03/11/13 wef
ASS. REC. BY: ARM

REF: C93/ASM 22006094/Rcy3

086B

LOE XPIRY: 2031/1/12

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 9334L
at Workshop m/s JS SPRAY WERKZ
of 5038, MK IWD PK 2 #01-355
Insured: ASM

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

194K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLW 9334L

Yr Regn:

2011 / NW

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W M3 coupe 4.0 SMT c.c 3999

Colour

BLACK

A/C: Insured / Std / NI / NA

Sp. Reading

136626

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBSK 692050E 698526

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

265/35 ZR19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

23/06/22

D.O.I.

28/06/22

Survey held at

JS SPRAY

Des. of Damages: Frt / Read / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 152K

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (3K-4K) / 3 days

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	0868
Vehicle No.:	SLN9334L
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jun 2022
Vehicle Make:	B.M.W.
Vehicle Model:	M3 COUPE 4.0 SMT ABS D/AB GAS/D NAV
Primary Colour:	Blue
Manufacturing Year:	2011
Engine No.:	20300051565B40A
Chassis No.:	WBSKG92050E698526
Maximum Power Output:	309.0 kW (414 bhp)
Open Market Value:	\$88,927.00
Original Registration Date:	23 Nov 2011
First Registration Date:	23 Nov 2011
Transfer Count:	3
Actual ARF Paid:	\$88,927.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	30 Apr 2031
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$47,316.00
COE Rebate Amount:	\$41,808.00
Total Rebate Amount:	\$41,808.00

The information contained herein is correct as at 29 Jun 2022

OK

BMW M Series M3 Coupe (COE till 06/2031)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price **\$198,000**

Depreciation ⓘ \$21,980 /yr

Reg Date 10-Nov-2011
(9yrs 1day COE left)

Mileage 97,000 km (9.1k /yr)

Manufactured ⓘ 2010

Road Tax ⓘ \$4,343 /yr

Transmission Auto

Dereg Value ⓘ \$48,583 as of today (change)

OMV ⓘ \$84,556

COE ⓘ \$53,932

ARF ⓘ \$84,556

Engine Cap 3,999 cc

Power 309.0 kW (414 bhp)

Curb Weight ⓘ 1,675 kg

No. of Owners ⓘ 6

Type of Vehicle Sports Car