

Claim	S2M0452F
Reference	CS3/ASM22006094/Rcy3e2 
Loss Date	23 June 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	27 Jun 2022 8:36:27 AM
Request Date	27 June 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident	SLN9334L
Vehicle	
Registration #	
Make	TPVD- BMW
Model	M3

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

HO Winnie

winnie.ho@axa.com.sg

Additional Instructions

- Messages1
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

▼

▼

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 TP PRI PDF.pdf.pdf	Other	Other	do not reply	
 ASM-LKKInvoice-AC2204095.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	4 July 2022

FAQ

English (default) ▾

Elaine Kuan ▾

Home

Service Requests

...

Statement

Survey Report

LKK AUTO CONSULTANTS PTE LTD (TP)

4 July 2022

LKKPhoto.pdf.pdf

Evidence

Photos

LKK AUTO CONSULTANTS PTE LTD (TP)

4 July 2022

SLN 9334L_IA.pdf.pdf

Reports & Statement

Others

LKK AUTO CONSULTANTS PTE LTD (TP)

30 June 2022

SHD3452T - OI GIA REPORT.pdf.pdf

Reports & Statement

Accident statement

HO Winnie

27 June 2022

SLN9334L - TP GIA REPORT.pdf.pdf

Reports & Statement

Accident statement

HO Winnie

27 June 2022

TP GIA REPORT (2).pdf.pdf

Reports & Statement

GIA Report

PODUVAL, Akash

27 June 2022

INSD GIA REPORT.pdf.pdf

Reports & Statement

GIA Report

PODUVAL, Akash

27 June 2022

FAQ English (default) ▼ Elaine Kuan ▼			SUBTYPE	AUTHOR	DATE UPLOADED
	Service Requests	...			
			Workshop	PODUVAL, Akash	27 June 2022

Correspondence