

ASS. REC. BY: Taught

REF:

CS / TM 22006101 / TCY3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Lim TSVeh No: SH 7204R Yr Regn: 2019, MayType: M.Car / M.Cycle / Bus / Van / Lorry / ② Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prim c.c. 1798Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 23854 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STDKBSF4603080546Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65X15R: 21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Winstake

Front Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 28/6/22Survey held at Comet WagonDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.B. / C. _____

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

Lim Tien Siong

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

CLS
LKK-

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	24/06/2022
Vehicle Reg. No.:	SH7204R	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Vehicle Reg. Date:	15/05/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2C16578	Chassis No:	JTDKB3FU603080546
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	2,448.42
Miscellaneous Items	11.00
Labour	1,520.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,979.42
+ GST 7.00% (S\$)	278.56
Nett Amount (S\$)	4,257.98

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Jun 2022)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SH7204R/27/06/2022 14:30

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Lim Tien Siong

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR TRUNK OUTER GARNISH	25.00	0.00	Rp *1,054.71 FL
2	1		*REAR TRUNK PRIUS	25.00	0.00	ner *62.14 FL
3	1		*REAR TRUNK HYBRID	25.00	0.00	ner *62.14 FL
4	1		*REAR TRUNK TOYOTA STAR	25.00	0.00	ner *81.43 FL
5	1		*REAR BUMPER	25.00	0.00	dl *551.89 FL
6	1		*REAR BUMPER REINFORCEMENT	25.00	0.00	? *378.32 FL
7	1		*REAR BUMPER LOWER COVER-BLACK	25.00	0.00	dl *654.96 FL
8	10		*REAR BUMPER CLIPS	25.00	0.00	ner *22.00 FL
9	1		*REAR BUMPER TOW COVER	25.00	0.00	X *82.70 FL
10	1		*REVERSE SENSORS	0.00	0.00	ner *135.70 F
11	1		*REAR TRUNK COMFORTDELGRO	0.00	0.00	ner *30.00 F
12	1		*REAR TRUNK 65521111	0.00	0.00	ner *30.00 F
13	1		*REAR TRUNK APPS	0.00	0.00	ner *40.00 F
				Sub Total (S\$)		3,185.99
				- List Item Discount on L Items (S\$)		737.57
				Total Parts (S\$)		2,448.42

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SH7204R/27/06/2022 14:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Lim Tien Siong

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

350

800.00

2 SPRAY PAINTING

New

500

600.00

3 R/I REVERSE SENSORS

New

30

120.00

Gross Labour Cost (S\$)

1,520.00

ComfortDelGro Engineering Pte Ltd/SH7204R/27/06/2022 14:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 9749544
WP 28/6/22 @ 5pm
L/S Resurvey after repair
tanpin@lkhauto.com
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 27.06.2022 13:52

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4299653

JC NO305521149

OMER

REGN NO:

SH 7204R

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)27.06.2022 09:15

DATE/TIME IN

YR OF MANU

15.05.2019

TARGET DATE

CHASSIS CODE

JTDKB3FU603080546

COMPLETION DATE/TIME:


UNT CARD NO.

JOB DESCRIPTION

cident Date: 24.06.2022
TURE: 3P 24.06.2022/C

NO LABOR CODE
0010 PB

DESCRIPTION
PANEL BEATING-SH 7204R-TP



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

lo.: SH 7204R LIMITS

Vehicle No.: SH 7204R

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard