ASS. REC. BY: Steve | CS/FC122061/4/Ecy3 |

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: XD8373R Yr Regn: 2/12/13

Type: M.Car / M.Cycle / Bus / Van / (Lorry) / Taxi / Prime Mover / Truck / Trailer or _____

Make: Volvo FE300 c.c 7146

Colour: White A/C: Insured / Std / NI / NA

Sp.Reading: 420564 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YV2H70D6EB620194

Gen. Cond: Good / (Fair) / Poor / Burnt

Steering: (Inorder) / Jammed / Leaked / Burnt or _____

Brake: (Inorder) / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 295/80R22.5

R: "

BS / (DUN) / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	4 mm	R/Bal.	4 mm
L/Bal.	4 mm	L/Bal.	4 mm
D.O.A.	17/5/99	D.O.I.	29/6/22

Survey held at UD TRUCKS

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Front LH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Waiting Estimate

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Report Format : _____

Lump Sum / I.B.I. ($ _____)

Survey Fee:	
Transportation:	$ + RS. SI
Photos	
Others	
TOTAL	

CamScanner