

ASS. REC. BY: Case

REF:

CS3/LPC22 004674/Rqy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GB6 1017Kat Workshop m/s KIM MOTORINGof GO JIN LAM HUAT #0226Insured: LPC

Policy No. _____


Claims No. 21/22/22/VC00/025811

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GB6 1017K Yr Regn: 31/05/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN NV350 c.c. 2488Colour WHITE A/C: Insured / Std / NI / NASp. Reading 116378 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1MC2E2620007700

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim orTyre Size: F: 195R15C

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or GREEN-MAX

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 14/05/22 D.O.I. 18/05/22Survey held at KIM MOTORINGDes. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/06/22 Submit PRS.

01/08/22 Submit LS \$10250, 12 days (Red \$5850, 36%)

Date/Time, File Pass to?

☐ : Preli. Report

1) 01/08 Typist

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 12

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Report Format: TP

Lump Sum / L.S. / 10250