(08/11/13) wef

ASS. REC. BY: Marcus

REF: CC4/LPC22006137/Upg3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNE5044Z

at Workshop m/s koh motor

of

Insured: XE 28634

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: $115k.

IDAC Accident Rport: Consistent? : **Yes** or **No**

GIA / PR Seen: Consistent? : **Yes** or **No**

Est. Repairs: 4 days Res.: **Yes** or **No**

Lum Sum: 1.B.1 % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS 581f

Vehicle: **IN / OUT**

Date: Person Contacted: A/A 870428

Veh No: SNE5044Z Yr Regn: 21/03/22

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**

Truck / Trailer or CA / 1.5D X

Make: Honda HRV c.c 1498

Colour Grey A/C: **Insured / Std / NI / NA**

Sp.Reading 436f T/Radio: **Insured / Std / NI / NA**

Eng/No:

C/No: JHMRV3800NS200133

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or

Brake: **Inorder / Jammed / Leaked / Burnt** or

Modi : **Nil / S/Rim / STD A/Rim** or

Tyre Size: F: 215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	24/06/22	D.O.I.	05/07/22

Survey held at

Des. of Damages : **Frt / Rear / O/S / N/S / U/C / Rooftop** or

frt n/s

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	Dep 11k.
10/8/22	informed Posoon P/P @ 4947.57

Date/Time, File **Pass** to? ☐ : **Preli. Report**

1) ☐ : **Final Report**

Date/Time, File **Return** to?

2)

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: ___S + RS, ___SI

Photos

Others

TOTAL