

Vantage Automotive Limited

(A Division of Vantage Automotive Limited)

Business Registration No. 192600045M GST Registration No. M2-0000551-1

305 Alexandra Road
159942 Singapore

Tel : 6272 8828
Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE



Estimate No. B9 5437	Date Estimated 22/06/2022	Page No. 1 of 2
	Prepared By Clement Chia Cher-Yang	

ESTIMATE REPAIR FOR Sime Darby Services Private Limited 305 Alexandra Road #02-01 Vantage Automotive Centre Singapore 159942	ACCOUNT 24748 MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay #24-01 Hong Leong Building Singapore 048581
---	--

REGN. NO. SMN3194B	CHASSIS NO. WBA6V120905N59240	REGN. DATE 31/07/2019	MODEL BMW 216I GRA	MILEAGE 35110
------------------------------	---	---------------------------------	------------------------------	-------------------------

DESCRIPTION	VALUE
TO CONDUCT OWN DAMAGED CLAIM AGAINST MSIG INS. DOA:21.06.2022	0.00
TO REMOVE AND REPLACE FRONT BUMPER AND FRONT RIGHT FENDER. <i>300x2</i>	600.00
TO REMOVE AND REPLACE FRONT RIGHT ALLOY RIM WITH BALANCING.	60.00
TO REMOVE AND REPLACE FRONT SUSPENSION TO FACILITATE THE JACKING OF CHASSIS TO MOUNT CAR ON CHASSIS ALIGNMENT BENCH INCLUDING REPLACEMENT OF DAMAGED PARTS. <i>(unloading)</i>	600 1,200.00
TO REMOVE/REFIT/REPLACE POWER STEERING RACK & PINION.	? 300.00
TO REPLACE FRONT BRAKE COMPONENTS WITH BRAKE TEST AND CHECK FOR LEAKS.	? 300.00
TO CONDUCT 4 WHEEL ALIGNMENT.	450.00
TO REMOVE/REFIT/REPLACE FRONT SENSORS. (DRILL HOLE)	120.00
TO SPRAY PAINT FRONT BUMPER AND FRONT RIGHT FENDER. <i>250x2</i>	500.00
TO CONDUCT ECU RE-PROGRAMMING AND ERASE OF ANY FAULT CODES.	450 600.00
SUNDRIES	20 100.00
TO REPAIR FRONT RIGHT SUSPENSION MOUNTING AREA.	? 150.00
TO SPRAY PAINT FRONT RIGHT SUSPENSION MOUNTING AREA AFTER REPAIR.	? 125.00
ACCIDENT TOWING TO VANTAGE.(NETT)	140.00
Total Labour 1:	4,645.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
31126879844	RH WISHBONE WITH MOUNTING	1	278.83	0.00	278.83
31128831646	RH WISHBONE BRACKET WITH MOUNT	1	187.06	0.00	187.06
31306887334	FRT RH SHOCK ABSORBER	1	314.50	0.00	314.50
31206874443	WHEEL HUB BEARING	1	498.24	0.00	498.24
31306862864	ENDLINK SUPPORT	1	102.43	0.00	102.43
31306853913	FRT AXLE ANTI ROLL BAR	1	426.21	0.00	426.21
33506861149	STABILIZER SUPPORT	1	25.01	0.00	25.01
31336892617	FRT TOP MOUNT	1	228.96	0.00	228.96

Vantage Automotive Limited

(Vision of Vantage Automotive Limited)

Business Registration No. 192600045M GST Registration No. M2-0000551-1

305 Alexandra Road
159942 Singapore

Tel : 6272 8828
Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE



Estimate No. B9 5437	Date Estimated 22/06/2022	Page No. 2 of 2
Prepared By Clement Chia Cher-Yang		

REGN. NO. SMN3194B	CHASSIS NO. WBA6V120905N59240	REGN. DATE 31/07/2019	MODEL BMW 216I GRA	MILEAGE 35110
------------------------------	---	---------------------------------	------------------------------	-------------------------

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
31306872562	SPRING RING COVER	1	11.95	0.00	11.95
31336860788	SPRING PAD LOWER	1	14.35	0.00	14.35
31316860787	SPRING PAD UPPER	1	20.06	0.00	20.06
31336861727	ABSORBER BUMSTOP	1	44.16	0.00	44.16
31336866504N	FRT COIL SPRING	1	238.46	0.00	238.46
31605A2E044	RH OUTPUT SHAFT	1	1,989.41	0.00	1,989.41
36116856087	ALLOY RIM 7.5X17 DBL SPK 549	1	938.26	0.00	938.26
51117932844	FRT BUMPER PRIMED PANEL	1	892.03	0.00	892.03
51117474260	FRT RH BLACK BUMPER GARNISH	1	51.92	0.00	51.92
51717473414	FRT RH WHEEL ARCH COVER	1	132.86	0.00	132.86
34116866297	FRT RH BRAKE DISC	1	179.17	0.00	179.17
32105A39027	ELECTRIC POWER STEERING RACK	1	5,349.65	0.00	5,349.65
41007382184	FRT RH FENDER	1	614.11	0.00	614.11
63115A32E02	RH HEADLAMP LED TECHNOLOGY	1	2,447.08	0.00	2,447.08
63118494844	FRT LIGHT CONTROL UNIT	1	875.33	0.00	875.33
63217491664	RH LED MODULE DAY DRIVE LIGHT	1	225.22	0.00	225.22
66209274428	ULTRASONIC SENSOR BLACK	1	241.15	0.00	241.15
31216876852	FRONT RIGHT KNUCKLE	1	558.96	0.00	558.96

Total Parts : **16,885.37**

Stevr CLKK)
28/6/22, 3:30pm

OD-M AL
Exm-?
PIP
My Bel y
6 dpr

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	S\$	4,645.00
Parts	S\$	16,885.37
Labour 2	S\$	0.00
Excess	S\$	0.00
Total GST @ 7%	S\$	1,507.13
Grand Total	S\$	23,037.50

Customer Name & Signature / Company Stamp

Date

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 22/06/2022 17:09 (SGT)
Date of Accident 21/06/2022 18:00 (SGT)
Exact Location of Accident Near 391A Orchard Rd, Singapore 238873
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMN3194B

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner SIME DARBY SERVICES PTE LTD
Company Reg No 1XXXXX065W
Email Address OPERATIONS@HERTZ.SIMEDARBY.COM.SG
Mobile Phone No (Phone) +65-90040114
Alternative Phone No (Office) +65-90040114

VEHICLE PARTICULARS

Manufacturer BMW
Model 216i
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 1499

INSURANCE COMPANY

Name of Insurance Company MSIG Insurance (Singapore) Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy Yes
Policy Number -
Cover Note Number -

DRIVER

Name of Driver THOMSON TANGTONG
Passport No/FIN XXX4696

Date Of Birth	28/05/1983
Occupation	Indoor
Date Of Driving Pass	11/04/2022
Driving experience	2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-90040114
Alt. Phone Number	-
Email Address	OPERATIONS@HERTZ.SIMEDARBY.COM.SG
Address	305 ALEXANDRA ROAD, #03-01
Address complement	-
Postcode	159942
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	CHRISTINE
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ACCIDENT REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SMN4751L
Vehicle Manufacturer	Nissan
Vehicle Model	Note
Vehicle Variant	-
Vehicle Colour	White
Vehicle Category	Private car

Name of Driver
NRIC No
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

OOI JUN LIANG
SXXXX045C
(Phone) +65-98502485

-
-
-
-
-
-
1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21/6/22 at about 1800, I was driving VEH 'A' and was about to EXIT TAKASHIMAYA CARPARK turning RIGHT to Orchard Turn. As I move off, I make sure there are no on-coming CARS on my Left and RIGHT. As I see its clear, I decided to drive out. Suddenly VEH 'B' hit onto my RIGHT area. No one was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



華強服務私人有限公司

ISLAND RECOVERY SERVICES PTE LTD

Address: 26 Chia Ping Road Singapore 619977

Telephone: 6747 7400

Email: admin@islandrecovery.com.sg

Facsimile: 6844 7233

Web: www.islandrecovery.com.sg

Co. Reg. No: 202114296E

GST Reg. No: 202114296E

CASH SALES / WORK ORDER

NO: 1293902

DATE: 21/6/22

ACCOUNT OF:

VAL - QUICK LANE

WORK DETAILS

Time of Order:

18.54

Time Reached Location:

Time Left:

Time End:

26.05

Waiting Time:

VEHICLE DETAILS

Vehicle No:

SMN 3194 B

Make & Model:

Bmw

LOCATION FROM

391A orchard rd

2ND TRIP

LOCATION TO

305 Alexandra Rd

TOWING / ROADSIDE ASSISTANCE

Additional Charges

☒ Using King Dolly

☐ Basement / Multi Carpark

☐ Midnight / Sunday / PH

☐ Exotic / Luxury Vehicle

☐ Crane Up / Winch Out

☐ Open Door

☐ Jump Start / Change Tyres / Change Battery

☒ Accident

☐ Loaded / Equipment

☐ Box

☐ ERP / Carpark:

☐ Dismantle Shaft / Brake

☐ Restricted Zone


☐ Others:

TRANSPORTATION

☐ Using Car Carrier

☐ Using King Dolly

☐ Restricted Zone



REMARKS:

ACCEPTANCE

+62 818970740

Thomson

Driver / Owner Handed Over By
(Name & Signature)

Taken Over By
(Name & Signature)

10843E
Island Recovery Services Pte Ltd
(Driver)

AMOUNT S\$

GST S\$

TOTAL S\$

Disclaimer: Island Recovery Services Pte Ltd and its staff and/or any person associated therewith cannot be held liable for any loss or damage that is incurred or may be incurred by any person as a direct or indirect result of the use of Island Recovery Services Pte Ltd's service.