

Enquire if Your Vehicle is Under Recall

Vehicle Recall Details

* ONLY INFORMATION ON VEHICLE RECALLS SUBMITTED FROM 9 APRIL 2007 IS AVAILABLE

Owner ID Type
Singapore NRIC

Owner ID
847C

Vehicle No.
SDW4323Z

Make/Model
HONDA/ VEZEL 1.5X A

Engine No.:
L15B4026790

Chassis No.:
RU11106786

Recall Details

Recall No.: R2016040221

Manufacturer Recall Date:

04 Apr 2016

Estimated Completion Year of Recall:

2021

Brief Description (As Provided by Motor Dealer):

A capacitor used in the engine idling-stop system may be insufficient in protecting against an overcurrent.

Date Rectified:

-

Hotline Information:

RS ORIENTAL PTE LTD (MR RYAN) at 86538383

For more details, contact RS ORIENTAL PTE. LTD.

Save as PDF

OK →

Print