



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22006151/Kvy3m4 Date: 13/07/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGW 4723S	Veh. Inspected	SLD 8478P	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10016004 /JT	Excess (\$)	0.00	
Assign From	MAYBIE CHUA	Assign Date	28/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN JETTA TSI (A)	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WVWZZZ16ZGM015832	Colour	METALLIC SILVER	
Odometer	44513 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	7 mm	
L/H Front Tyre	205/55 R16	PIRELLI	7 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	7 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/06/2022	Inspection Date	29/06/2022	
Survey held at	OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	