

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|---|------------------------|-----------------|-------|-------------------|--|
| | EQ INSURANCE C | OMPANY LTD | F | Ref: | CS/EQI22006163/y3 | |
| | 5 MAXWELL ROAD #17-00 TOWER BL MND COMPLEXSI | OCK | [| Date: | 28/06/2022 | |
| | | | (| Code: | EQI | |
| 1. | 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | | Veh. Inspected | | SMP 5552C | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | DL22HO00164/LL | Excess (\$) | | 0.00 | |
| | Assign From | LYNN LIM | Assign Date | | 28/06/2022 | |
| 2. | 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | | c.c | | 0 | |
| | Engine No. | HIDDEN | Year of Reg. | | | |
| | Chassis No. | | Colour | | | |
| | Odometer | - | Steering | | | |
| | Brakes | | Modification | | | |
| | General | | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | | | | mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | | | | mm | |
| | L/H Rear Tyre | | | | mm | |
| 4. | Description of Damages | | | | | |
| | | | | | | |
| 5. | 5. General Information | | | | | |
| | Accident Date | 24/06/2022 | Inspection Date | ! | | |
| | Survey held at | 27A TANJONG PENJURU | | | | |
| | Repairer | TRANS EUROKARS PTE LTD | | | | |
| 5a. Remarks | | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |