



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS3/SMO22001966/Avy3e2-1	
			Date: 20/07/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 289Z	Veh. Inspected	GBH 3608L	
Policy No.	D20MTHCVE001400	Coverage (\$)	0.00	
Claim No.	CMTD2200770/GPL	Excess (\$)	0.00	
Assign From	GNOH PAU LOONG	Assign Date	28/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	VM20115888	Colour	SILVER	
Odometer	65483 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14C	GOODYEAR	6 mm	
L/H Front Tyre	175/70 R14C	GOODYEAR	6 mm	
R/H Rear Tyre	175/70 R14C	GOODYEAR	6 mm	
L/H Rear Tyre	175/70 R14C	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/02/2022	Inspection Date	02/03/2022	
Survey held at	25 Kaki Bukit Rd 4, #05-65/66/67/68			
Repairer	ISAFE GARAGE			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	