

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LONPAC INSURA	NCE BHD	Ref:	CS3/LPC22004291/Tvy3e2-1	
	300 BEACH ROAD #17-04/07 THE CC	NCOURSESINGAPORE 199555	Date:	26/07/2022	
			Code:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SBN 8226R	Veh. Inspected	SMZ 8601Y	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	22/22/22/VP05/025757	Excess (\$)	0.00	
	Assign From	GERALD POH	Assign Date	28/06/2022	
2.	Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	RU31260493	Colour	WHITE	
	Odometer	77968 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
	L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
	R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
	L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	04/05/2022	Inspection Date	10/05/2022	
	Survey held at	SG AUTO PTE LTD			
		25 KAKI BUKIT ROAD 4 #05-34 SINGAPORE 417800			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				