



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: LOH CYNTHIA			Ref: CS3/ASM22002098/Eqy3e2-1 Date: 24/08/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	SHC 5684H	Veh. Inspected	SJA 5751J
	Policy No.	VFX/P2413997	Coverage (\$)	0.00
	Claim No.	S2M03UZ7	Excess (\$)	0.00
	Assign From	LOH CYNTHIA	Assign Date	08/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA WISH	c.c	1794
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	ZNE100375450	Colour	SILVER
	Odometer	260379 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	DUNLOP	5 mm
	L/H Front Tyre	195/65 R15	DUNLOP	5 mm
	R/H Rear Tyre	195/65 R15	DUNLOP	5 mm
	L/H Rear Tyre	195/65 R15	DUNLOP	5 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	04/03/2022	Inspection Date	29/06/2022
	Survey held at	MASTER CAR SPRAY SERVICE 36 TOH GUAN ROAD EAST #01-48 ENTERPRISE HUB SINGAPORE 608580		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	