ASS. REC. BY: Kenneth

REF: C121 22008210 lk

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ [H] Express

of _____

Insured: _____ 3550

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKU 7163B Yr Regn: 08, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or (A)

Make: Mer CLA 180 c.c 1595

Colour White A/C: Insured / Std / NI / NA

Sp.Reading 118753 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD1173422N234969

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modl : NII / S/Rim / STD A/Rim or _____

Tyre Size: F: 225/40R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	8 mm	R/Bal.	8 mm
L/Bal.	8 mm	L/Bal.	8 mm
D.O.A.	1/22	D.O.I.	4/7/2022

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or & Rm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	GIA & EH not ready

no, File Pass to? _____

☐ : Prell. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

no, File Return to? _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ Tech Invs ($ _____)

☐ Weekend ($ _____)

Format :

Sum / I.B.I: ($ _____)

Survey Fee: _____

Transportation: ___S + RS. ___SI

Photos

Others

TOTAL