SN09226T0009 / National Assessment Centre Services [408933] ENTRY DATE & TIME: 29/06/2022 17:21 (SGT) SUBMITTED BY: Chew Hsiao Tong VERSION: 1 (29/06/2022 17:21 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT Date of Submission 29/06/2022 17:21 (SGT) Reported by Driver Date of Accident 27/06/2022 09:10 (SGT) Exact Location of Accident Lornie Hwy, Singapore Additional Location Information TOWARDS BRADDELL ROAD Country/State of Loss Singapore **DETAILS OF OWN VEHICLE** Vehicle Registration Number **GBJ6626D** INSURED/POLICYHOLDER Is company? Yes Name Of Registered Owner STRAITS TEAMWORK PTE LTD Company Reg No 1XXXXX956G Email Address stwork@gmail.com Mobile Phone No (Phone) +65-90946263 Alternative Phone No (Office) +65-62826580 VEHICLE PARTICULARS Manufacturer Fiat Model Fiorino Variant Exact purpose for which vehicle was being used at time of accident **Employment** Are you claiming under your own insurance policy for repair to your vehicle? Yes Vehicle Category Commercial vehicle Transmission Auto CC 1248 **INSURANCE COMPANY** Name of Insurance Company Liberty Insurance Pte Ltd Policy Number / Cover Note Number SI21V06086/VCH/R01

PERIYASAMY KARUPPIAH

SXXXX464A

14/06/1966

Outdoor

DRIVER

NRIC No

Name of Driver

Date Of Birth

Occupation

Date Of Driving Pass 25/09/2008 Driving experience 13 YEARS AND 9 MONTHS Gender Mobile Number (Phone) +65-90946263 Alt. Phone Number Email Address stwork@gmail.com Address BLK 12 LORONG 7 TOA PAYOH #02-475 Address complement Postcode 310012 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured **Employee** Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? Nο If yes, against whom? CIRCUMSTANCES OF ACCIDENT PLEASE REFER TO SKETCH AND ATTACHMENT ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number YN5895G Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Commercial vehicle Name of Driver

Contact Number

Address	<u>-</u>
Address complement	-
Postcode	-
Insurance Company Name	<u>-</u>
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	<u>-</u>

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
 of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

& Time

REFFER W

- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date

pmpetimisu

Witnessed by Reporting Centre Personnel

Sketch Plan



time: 9.10 am Location: Lornie high way (Tunnel) before large post 74 from work place Vic PIE - Lornie tunnel to braddell road, Hapren: During driving when I change from have (2) to large (happen my vehicle go in to hit on vear body and damaged the RIS dange Light drepted for appears long (No 5895 E) No injuries other parry driver. Note () Dived Vehicle (1876 61260) left side door (Larn seem head dight and 8rde of body with mimor damaged ltc. (a) No traffic Police at the Place. (3) Normal traffic.	Dute:	27/06/2024
touth Lornie ligh way (Tunnel) before large post 74 from work place Via PIE - Lorniz tunnel to praddell road, Hapren : During driving when I change from Lane (2) to Lane (happen my vehicle go in to hit on rear body and damaged the RIS dange light droped for aprome long (IN 5895 E) No injures other parmy driver. Note (1) Divel Vehicle GB3 6626D left Side door Glam screen head light and side of body with mimor damageel Otc. (2) No traffic Police at the Place.	time	9.10 aun
Hapren : During driving when I change from Lane 2) to Lane I happen my voticle go in to buit on rear body and damaged the RIS danger Light dropped for aprome long (IN 5895 E) No injures other parry driver. Note 1 Doved Vehicle GB3 6626D left Fide door glam streen head leght and 8ide of body with mimor damaged Otc. 1 No trafic Police at the Place.	Localm	Lornie ligh way (7 unnel) before (my port 74
Hapren : During driving when I change from Lane 2) to Lane I happen my voticle go in to buit on rear body and damaged the RIS danger Light dropped for aprome long (IN 5895 E) No injures other parry driver. Note 1 Doved Vehicle GB3 6626D left Fide door glam streen head leght and 8ide of body with mimor damaged Otc. 1 No trafic Police at the Place.		from work place VIE PIE - Lorniz tunnel to
Happen During driving when I change from Lane (2) to Lane I happen my vehicle go in to hit on vear body and damaged the RIS danger Light dropod for aprome long (yn 5895 E) No injures other parry driver. Note (1) Drived Vehicle (1876-1626) left Side door ylan streen head higher and side of body with mirror damaged Otc. (2) No traffic Police at the Place.		braddell road.
Note ① Drived Vehicle GBJ 6626D left Side door glan screen head leght and side of body with mimor damaged sto. ① No traffic Police at the Place.		
Note ① Drived Vehicle GBJ 6626D left Side door glan screen head leght and side of body with mimor damaged sto. ① No traffic Police at the Place.	Hapren	· During driving when I change from Lane (2)
Note ① Drived Vehicle GBJ 6626D left Side door glan screen head leght and side of body with mimor damaged sto. ① No traffic Police at the Place.		to Lane I happen my valuele as in to
Note ① Drived Vehicle GBJ 6626D left Side door glan screen head leght and side of body with mimor damaged sto. ① No traffic Police at the Place.		but on war body and damined the RIS dances
Note ① Drived Vehicle GBJ 6626D left Side door glan screen head leght and side of body with mimor damaged sto. ① No traffic Police at the Place.		listed Around for sprante Long (1/N 5895 E)
Note ① Drived Vehicle GBJ 6626D left Side door glan screen head leght and side of body with mimor damaged sto. ① No traffic Police at the Place.		NO injuies other party driver.
	Note	1 Doved Vehicle GBJ 6626D left side door
		years sever head light and side of body with
		nimor damaged ste.
		1 No trafic Police set the Place.
3 Normal truthic.		
		3 Normal truffic.

Declaration

We declare the foregoing particulars are true in every respect.

Tean do

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



