

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT/22006242/Key3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBL13414

at Workshop m/s

Asia Motors

of

Insured:

SMT493B

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

882k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 24855

Date / Time

Action / Instruction

20710k.

7/7/22 4/5 @ 6300 informed AH long (Red. 14,090f, 692)

Veh No:

GBL13414

Yr Regn:

23/103/21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Toyota Hiace DXL-8c.c 2754

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

37057

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GDH 2011054265

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 / 60R 14 Yokohama

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

26/06/22

D.O.I.

30/06/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

TOTAL

Report Format :

TP

Lump Sum / I.B.I: (\$

6300f

)


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	686K
Vehicle Details	
Vehicle No.:	GBL1341Y
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jun 2022
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 2.8 AUTO
Primary Colour:	Silver
Manufacturing Year:	2021
Engine No.:	1GD8676794
Chassis No.:	GDH2011054265
Maximum Power Output:	-
Open Market Value:	\$34,917.00
Original Registration Date:	23 Mar 2021
First Registration Date:	23 Mar 2021
Transfer Count:	1
Actual ARF Paid:	\$1,746.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Mar 2031
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$28,485.00
COE Rebate Amount:	\$24,855.00
Total Rebate Amount:	\$24,855.00

The information contained herein is correct as at 30 Jun 2022

OK



Post an Advertisement

Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Brand New Clutch! Wear & Tears Replaced!



Original Novitec with Original
Novitec Exhaust! High Loan &
Trade In Available!
Warehouse Exotics StarAd

PRIME MOTOR & LEASING
(CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)
With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.

Sort by 20 results/page

15 vehicles










toyota hiace dx

Any Category

Advanced Search



Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	toyota hiace dx		Any	Any	2021	Any	Any	Any	Available
	Toyota Hiace 2.8A DX		\$89,800	\$10,370 /yr	26-Feb-2021	2,754 cc	20,149 km	Van	Available
	Fuel Type: Diesel								
	Genuine low mileage of 20,149km only! 1 ownerships with original manufacturer paintwork! Premium warranty + further lucrative packa...								
	Car (S) Pte Ltd								
	Posted: 30-Jun-2022								
	Toyota Hiace 2.8A DX		\$96,800	\$11,080 /yr	26-Mar-2021	2,754 cc	-	Bus	Available
	Fuel Type: Diesel								
	As good as new! 2021 registered 5 door auto bus. Well kept by previous owner. 100% loan available.								
	Think One Automobile & Trading								
	Posted: 30-Jun-2022								
	Toyota Hiace 2.8A DX		\$90,800	\$10,480 /yr	26-Feb-2021	2,754 cc	-	Van	Available
	Fuel Type: Diesel								
	No admin fee! Instalment from \$9xx/mth. Zero downpayment & full loan available. Open daily 10am till late. Night appt till 12midnight...								
	Posted: 30-Jun-2022								
	Toyota Hiace 2.8A DX		\$86,000	\$10,020 /yr	28-Jan-2021	2,754 cc	-	Van	Available
	Fuel Type: Diesel								
	I-Deal Auto Trading Pte Ltd								
	Posted: 29-Jun-2022								
	Toyota Hiace 2.8A DX		\$87,500	\$10,040 /yr	17-Mar-2021	2,754 cc	-	Van	Available
	Fuel Type: Diesel								
	Excellent condition, Toyota Hiace 5dr auto, well maintained and taken care by previous owner, no repair needed. No hidden cost. High tr...								
	I-Deal Auto Trading Pte Ltd								
	Posted: 29-Jun-2022								
	Toyota Hiace 2.8A DX		\$87,999	\$10,080 /yr	24-Mar-2021	2,754 cc	-	Van	Available
	Fuel Type: Diesel								
	New Condition. 3 Months Warranty And Free Servicing. 100% Loan Can Submit. Bank / In House Loan Support. Low Interest Rate. Cust...								
	ABS Bus Pte Ltd								
	Posted: 29-Jun-2022								
	Toyota Hiace 2.8A DX		\$89,800	\$10,280 /yr	24-Mar-2021	2,754 cc	-	Van	Available
	Fuel Type: Diesel								
	Most reliable and high demand big van. 5 door auto diesel unit. Excellent condition. Smooth engine and gearbox. Low mileage. Flexible l...								
	ABS Bus Pte Ltd								
	Posted: 29-Jun-2022								
	Toyota Hiace 2.8A DX		\$92,800	\$10,650 /yr	17-Mar-2021	2,754 cc	-	Van	Available
	Fuel Type: Diesel								
	1 Owner Unit, Customer previously bought double transfer. Still under warranty and free servicing. Vehicle is in tip top condition and well...								

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	27/06/2022 18:52 (SGT)
Reported by	Driver
Date of Accident	26/06/2022 10:55 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE - CHANGI
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBL1341Y
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	ALPHINE BUILDERS PTE LTD
Company Reg No	200515686K
Email Address	ANDREAHOI@SFLEASING.COM.SG
Mobile Phone No	(Phone) +65-97168811
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Hiace
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	3000

INSURANCE COMPANY

Name of Insurance Company	ERGO Insurance Pte. Ltd.
Policy Number / Cover Note Number	DMCG21008096

DRIVER

Name of Driver	SHAIK FARID BIN ABDUL RAHIM
NRIC No	S8506871G
Date Of Birth	26/02/1985
Occupation	Outdoor

Date Of Driving Pass	21/03/2006
Driving experience	16 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-89254715
Alt. Phone Number	-
Email Address	ANDREAHOI@SFLEASING.COM.SG
Address	201 MARSILING DR #12-122 S 730201
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMT493B
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-

Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage -
 Details of property damaged in accident -
 No. Of Passenger (Including Driver) -

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	SHAIK FARID BIN ABDUL RAHIM
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	GBL1341Y
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (Driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan

please refer to attached sketch.

Describe Circumstance of the Accident

I slow down due to road works, suddenly
I felt an impact from behind + realise
that vehicle B + hit onto my rear.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

2



24 EJP 446050.11
 6/16/2002 89254715

26/6/2002
 1055AM
 GBL13417



Asia Motorsports Solution Pte Ltd

37A Everitt Road , Singapore 428586

VEHICLE REPAIR ESTIMATE

Vehicle Registration No: GBL1341Y

Date: 29 June 2022

Qty	Description	Condition	Repaire's Estimate
-----	-------------	-----------	--------------------

SPARE PARTS - LIST ITEMS

1	Rear bumper assy	Dented/Warped	584.10 \$ 1,200.00
4 pcs	Rear bumper bracket @ 22.00	Warped/Necessary	88 \$ 375.00
2	Rear bumper retainers @ 105.10	Warped/Necessary	210.20 \$ 385.00
1	Rear bumper upper LH	Warped	\$ 260.00 X
1	Rear bumper step bracket	Warped	242.80 \$ 260.00
1	Rear taillamp RH	Cracked	388.60 \$ 1,150.00
1	Rear taillamp LH	Cracked	388.60 \$ 1,150.00
1	Rear tailgate assy	Dented/Warped	2192.10 \$ 2,245.00
1	Rear tailgate lock actuator motor	Malfunction	345.20 \$ 620.00
1	Rear tailgate lock latch	Malfunction	\$ 380.00 X
1	Rear tailgate lock cover	Bent	105.10 \$ 180.00
1	Rear tailgate weatherstrip	Torn/Necessary	\$ 320.00
1	Rear tailgate outer garnish	Warped	\$ 280.00
1	Rear tailgate inner board	Warped	288.40 \$ 320.00
1	Rear tailgate vehicle lamp (1 set)	Malfunction	\$ 280.00 X
1	Rear tailgate dampers (1 set)	Bent/Necessary	\$ 520.00 X
1	Rear floor panel	Repair	\$ - X
1	Rear end panel	Dented	801.10 \$ 950.00
1	Rear end panel inner	Dented	841.60 \$ 989.00
1	Rear exhaust pipe muffler	Bent	\$ 600.00 X
			\$ 12,464.00
Less 25%			\$ 3,116.00
			\$ 9,348.00

Not Authorized
her
30/6/22

L/S \$ 6300
6 days

Submit to us

Whaphle After Rep-

Asia Motorsports Solution Pte Ltd

Vehicle Registration No: GBL1341Y

Date: 29 June 2022

Total cost of parts c/f

\$ 11,300.00

S/No	Description	Repairer's Estimate
------	-------------	---------------------

LABOUR

1	To cut, weld, straighten affected areas and replace damaged parts.	\$ 2,600.00 1000
2	To putty and spray painting the affected areas. Job Allowance.	\$ 2,600.00 850
3	To check rear lighting and wiring.	\$ 140.00 30
4	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 11 280.00 X
5	To apply anti rust proofing to the affected areas.	\$ 300.00 80
6	To remove and install rear windscreen to facilitate the repair	\$ 280.00 120
7	To remove and install rear tailgate assy.	\$ 280.00 60
8	To remove and install taillamp & vehicle license lamp.	\$ 11 280.00 X
9	To remove and install rear vehicle license plate.	\$ 11 280.00 X
10	To remove and install rear bumper assy.	\$ 11 280.00 X
11	To remove and install rear bumper reverse sensor	\$ 280.00 50
12	To remove and install rear end panel assy.	\$ 11 280.00 X
13	To remove and install exhaust system.	\$ 11 280.00 X
14	To install and remove the rear lock components.	\$ 11 280.00 X
15	To check central door lock system.	\$ 11 300.00 X
16	To conduct chassis alignment.	\$ 11 350.00 X

Grand Total:

\$ 20,390.00

P-707980

252

530985

405

2190

7904.85

202
6323

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: