

# MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

<b>TO</b>	: AIG	<b>DATE</b>	: 26-Jul-22
<b>ATTENTION</b>	: MOTOR CLAIMS DEPT	<b>JOB TYPE</b>	: TP CLAIM
<b>ESTIMATE REPORT</b>	:		
<b>VEHICLE DETAILS</b>			
<b>VEHICLE NO</b>	: SMP4266K		G871099516
<b>MODEL</b>	: HONDA FREED 1.5G A		
<b>CHASSIS NO</b>			
<b>ACCIDENT DETAILS</b>	<b>DATE</b> : 26-Jun-22		
	<b>TIME</b> : 10:45HRS		
<b>THIRD PARTY REQUESTOR / CONTACT</b>	: JACK LI		

## CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR <i>Repair</i>	1	\$ 1,855.30	\$ 1,855.30
2	FRONT DOOR STICKER <i>new</i>	1	\$ 120.00	\$ 120.00
3	REAR SLIDING DOOR <i>Dented</i>	1	\$ 2,355.80	\$ <del>2,355.80</del>
4	REAR SLIDING DOOR STICKER <i>new</i>	1	\$ 110.50	\$ 110.50
5	ROCKER PANEL <i>Repair</i>	1	\$ 860.50	\$ 860.50

TOTAL PRICE \$ 5,302.10

LESS 20% \$ 1,060.42

**SUB TOTAL PRICE \$ 4,241.68**

*1205*  
*964*

*+*  
*+*  
*1205*  
*+*

## CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, WELDING, CUTTING, GRAZING ADJUST, KNOCK STRAIGHTEN	\$ 1,000.00	<i>400</i>	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX	\$ 1,000.00	<i>800</i>	
3	REMOVE AND REFIX FRONT DOOR MECHANISM	\$ 120.00	<i>+</i>	
4	REMOVE AND REFIX REAR SLIDING DOOR MECHANISM	\$ 180.00	<i>80</i>	

**TOTAL**

**\$2,300.00**

*1280*

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 4,241.68  
TOTAL LABOUR COST : \$ 2,300.00  
TOTAL REPAIR COST : \$ 6,541.68

**APPROVED DETAILS**

**SURVEYOR :**  
**CONTACT NO :**

**FAX :**

**PART BY PART / LUMP SUM :**  
**NO OF DAYS :**

Adrian Li  
H/S 26/07/22  
03 Days

total: 2244  
C/S: 1.8k

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: