

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAI	L INSURANCE (S) PL	R	ef:	CS/AGI22006262/Dvy3q2	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	28/11/2022	
			С	ode:	AGI	
1.	. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMK 7855S	Veh. Inspected		SHD 4750B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10016046 /JT	Excess (\$)		0.00	
	Assign From	MAYBIE CHUA	Assign Date		30/06/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	KMHC851CVLU190022	Colour		BLUE	
	Odometer	249875 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST LAKE		5 mm	
	L/H Front Tyre	195/65 R15	WEST LAKE		5 mm	
	R/H Rear Tyre	195/65 R15	WEST LAKE		5 mm	
	L/H Rear Tyre	195/65 R15	WEST LAKE		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR & N/S FRONT PORTION. DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	25/06/2022	Inspection Date		30/06/2022	
	Survey held at	rvey held at Blk 9 Sector C #01-42, Sin Ming Industrial Estate				
	Repairer	BIFROST AUTO PTE LTD				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					

14 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: