

ASS. REC. BY:

REF:

AGZ/22006263/1kg

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_ of Tropical

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_ (Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SVD 87614 Yr Regn: 01.22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Camry c.c. 2487

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 3884 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTNBA3HKX.03005486

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 215/55R17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA (MIC) OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 25/6/22

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 12/7/2022

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Rear body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to? : Prell. Report

1) : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

Table with 2 columns and 5 rows for recording fees and totals.

Report Format :

Lump Sum / I.B.I: (\$)

N/A

MO

AXA INSURANCE

# Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M / s : **Auto & General Insurance (Singapore) Pte Ltd**  
 190, Clemenceau Avenue, #03-01,  
 Singapore Shopping Centre,  
 Singapore 239924

Estimate bill : TT 20 / 22 / TP / WT

Registration No : SND8761Y

Attn : Motor Claims Department  
 Tel : 6221 2111  
 Fax : 6725 0611

Make model : Toyota Camry  
 Hybrid

*NOT Insured  
 Recovery Bypass  
 4 days*

Mileage : \_\_\_\_\_ Date : 07 / 07 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SLN4387S AND  
 SND8761Y ALONG MACPHERSON ROAD ON 25 JUNE 2022 AT ABOUT 1350HRS.**

1pc	Rear LH door	\$	<i>12</i>	1,620.00	X
1pc	Rear LH door outer moulding	\$	<i>12</i>	190.00	X
1pc	Rear LH quarter glass	\$	<i>12</i>	999.00	X
1pc	Rear LH quarter glass outer moulding	\$	<i>12</i>	621.00	X
1pc	Rear LH door pillar outer garnish (Stand up)	\$	<i>12</i>	173.00	X
1pc	Rear LH door pillar weather strip (Stand up)	\$	<i>12</i>	138.00	X
1pc	Rear LH door weather strip (Small)	\$	<i>12</i>	173.00	X
1pc	Rear LH door weather strip (Big)	\$	<i>12</i>	276.00	X
1pc	Rear LH fender	\$	<i>12</i>	1,517.00	X
1pc	Rear LH fender stone guard protection sticker	\$	<i>12</i>	69.00	✓
1pc	Rear bumper	\$	<i>12</i>	690.00	X 7
1pc	Rear bumper side retainer (LH)	\$	<i>12</i>	156.00	X
1pc	Rear wheel bearing (LH)	\$		759.00	7
	Sub A total :	\$		7,381.00	
	Less 25% discount :	\$		1,845.25	
	A total :	\$		5,535.75	
	Special Net Item :				
1pc	Rear LH, Michelin Primacy 3 ST, 215 / 55 R17 tyre	\$	<i>12</i>	293.00	X
1pc	Rear LH 17 inch wheel	\$	<i>12</i>	2,087.00	✓
	B total :	\$		2,380.00	
	Remove and refit rear windscreen.	\$	<i>12</i>	250.00	X
	Total amount of Page 1 :	\$		8,165.75	

Tropical Tech Automobile Services

  
 ( Authorised Signature )  
 William Tan



**LKK Auto Consultants hence notify  
 the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M / s : **Auto & General Insurance (Singapore) Pte Ltd**  
 190, Clemenceau Avenue, #03-01,  
 Singapore Shopping Centre,  
 Singapore 239924

Estimate bill : TT 20 / 22 / TP / WT

Registration No : SND8761Y

Attn : Motor Claims Department  
 Tel : 6221 2111  
 Fax : 6725 0611

Make model : Toyota Camry  
 Hybrid

Mileage :

Date : 07 / 07 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SLN4387S AND  
 SND8761Y ALONG MACPHERSON ROAD ON 25 JUNE 2022 AT ABOUT 1350HRS.**

Remove and transfer rear LH door necessary attachment spart part items.

Remove and refit rear LH door, rear LH door outer moulding, rear LH quarter glass, rear LH quarter glass outer moulding, rear LH door pillar outer garnish (Stand up), rear LH door pillar weather strip (Stand up), rear LH door weather strip (Small), rear LH door weather strip (Big).

\$ *na* 500.00 *3501 X*

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear bumper, rear bumper side retainer (LH).

Heat / weld / cut / renew rear LH fender, heat / weld / beating / pull / straighten / alignalign rear chassis frame by Chassis Alignment jack.

\$ 1,000.00 *600 400*

Remove and refit rear LH wheel.

Balancing rear LH wheel.

\$ 50.00 *201*

Remove and refit rear wheel bearing (LH).

\$ 150.00 *7*

Wheel alignment test.

\$ 100.00 *601*

Diagnostic rear bumper parktronic sensor by HHT.

\$ *na* 100.00 *X*


Under coating on rear damaged portion.

\$ *na* 200.00 *X*

Total amount of Page 2 :

\$ 2,100.00

Tropical Tech Automobile Services

  
 ( Authorised Signature )  
 William Tan



# Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : [tasc303@singnet.com.sg](mailto:tasc303@singnet.com.sg)

M/s : **Auto & General Insurance (Singapore) Pte Ltd**  
190, Clemenceau Avenue, #03-01,  
Singapore Shopping Centre,  
Singapore 239924

Attn : Motor Claims Department  
Tel : 6221 2111  
Fax : 6725 0611

Estimate bill : TT 20 / 22 / TP / WT

Registration No : SND8761Y

Make model : Toyota Camry  
Hybrid

Mileage :

Date : 07 / 07 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SLN4387S AND  
SND8761Y ALONG MACPHERSON ROAD ON 25 JUNE 2022 AT ABOUT 1350HRS.**

Putty / primer application, spray painting on rear LH door, rear LH fender, rear bumper.

\$ 1,200.00 *book*

Balance brought forward from Page 1 :

\$ 8,165.75

Balance brought forward from Page 2 :

\$ 2,100.00

**Grand final amount :**


**\$ 11,465.75**

Tropical Tech Automobile Services



( Authorised Signature )  
William Tan

Date of accident: 15/06/22 Time: 1350 Location: Macpherson Rd  
 My Vehicle A: SND8761Y Vehicle B: SLN4387S Vehicle C:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer Police Report No.  
 T/20220625/2022

- Claim OD/TP at Ah Lim Motor
- Claim OD/TP at other workshop
- Reporting Only

Remarks: Please forward a copy of my efile accident report to:  
 My workshop: Tropical Success Auto Centre  
 Email address: tsac303@singnet.com.sg  
 & myself:  
 Email address:

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

Policyholder Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Person's Signature  
 Name:  
 NR/CFIN No.:



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	29/06/2022 15:01 (SGT)
Reported by	Driver
Date of Accident	25/06/2022 13:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	MACPHERSON RD
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SND8761Y
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CHUA AH GUAN (CAI YAYUAN)
NRIC No	SXXXX377G
Email Address	STALLOB96@GMAIL.COM
Mobile Phone No	(Phone) +65-90306666
Alternative Phone No	-

## VEHICLE PARTICULARS

Manufacturer	Toyota
Model	CAMRY ASCENT HYBRID CVT
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2487

## INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Policy Number / Cover Note Number	GA606896

## DRIVER

Name of Driver	CHUA YU HANG
NRIC No	SXXXX596G
Date Of Birth	27/06/1996
Occupation	Indoor