



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22006266/Uvy3m4	
			Date: 08/07/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 8016M	Veh. Inspected	SMP 9801H	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2202262/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	30/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	KIA CERATO (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	KNAFW411MA5200641	Colour	BROWN	
Odometer	159783 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 ZR17	FALKEN	6 mm	
L/H Front Tyre	215/45 ZR17	FALKEN	6 mm	
R/H Rear Tyre	215/45 ZR17	APLUS	6 mm	
L/H Rear Tyre	215/45 ZR17	APLUS	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/06/2022	Inspection Date	30/06/2022	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	