



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22006269/Avy3q2 Date: 14/12/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 7848H		Veh. Inspected	SLH 5601Z
Policy No.			Coverage (\$)	0.00
Claim No.	C10016091 /JT		Excess (\$)	0.00
Assign From	MAYBIE CHUA		Assign Date	30/06/2022
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS		c.c	1598
Engine No.	HIDDEN		Year of Reg.	2009
Chassis No.	MR053ZEE106158126		Colour	RED
Odometer	319874 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	TOURADOR	6 mm	
L/H Front Tyre	195/65 R15	TOURADOR	6 mm	
R/H Rear Tyre	195/65 R15	TOURADOR	6 mm	
L/H Rear Tyre	195/65 R15	TOURADOR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/06/2022		Inspection Date	04/07/2022
Survey held at	UNIMOTOR COMPANY 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	