



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Ref: CS/AGI22006272/Kvy3m4

Date: 06/07/2022

Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNE 4621P	Veh. Inspected	SCR 90J
Policy No.		Coverage (\$)	0.00
Claim No.	C10016108 /JT	Excess (\$)	0.00
Assign From	MAYBIE CHUA	Assign Date	30/06/2022

2. Vehicle Particulars & Condition

Make & Model	SKODA SUPERB (A)	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	TMBBD9NP1J7601868	Colour	METALLIC BLACK
Odometer	56997 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/40 ZR19	YOKOHAMA	8 mm
L/H Front Tyre	235/40 ZR19	YOKOHAMA	8 mm
R/H Rear Tyre	235/40 ZR19	YOKOHAMA	8 mm
L/H Rear Tyre	235/40 ZR19	YOKOHAMA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/05/2022	Inspection Date	04/07/2022
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
--	-----------------------