ASS. REC. BY: Thuan REF: (S3/CT)	27003470/4473
	SSIGNMENT
From: Date:  Estimated Cost:  OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Veh No: SL 6655UH Yr Regn: 10/10//6 Type: M.Car) M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
To Inspect Vehicle No:	Truck / Trailer or
at Workshop m/s	Make: Hundai tucson c.c 1999
of	Colour black A/C: Insured/Std/NI/NA
Insured:	Sp.Reading /S// 8/ T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No.	C/No: hm H = 38   3 M + 1 u z 98:655
Cum Inquired	Gen. Cond: Good/ Fair / Poor / Burnt
	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)  Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
Make Of Vell.	Modi: NII / S/Rim / STD A/Rim or
	Tyre Size: F: 225/50 R/8
(Policy Condition)	R: 225/50118
Remark: The veh had commenced its  repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
	TOYO/YOKO or
Bal. or Market Value: 68k	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. C mm
Est. Repairs: days Res.: Yes or No	D.O.A. 1214/22 1800
Lum Sum: % 3 Val.: Yes or No	Survey held at HHEK 500 Motor
CA / REV / REP. / 24 HRS	Des. of Damages: Frt) Rear O/S / N/S / U/C / Rooftop or
Date:Person Contacted: Vehicle: IN / OUT	and the property the property the property that the property the property that the p
Date / Time   Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
MV: 68K	
relight: 36287	
W: 31713 SUBMIT DRS DEDORT	
rr. 1/4-12/	
27/09/2022 Submit L/S \$18,000.00 @ 13days (Red \$4,900.00/ 21%)	
Date/Time, File Pass to? : Preli. Report Da	ys Of Repair: 42
1) : Final Report Re	Our could be a first
Date/Time, File Return to?	
2) Add Fee:	: Site Insp (\$ )S+RS,SI
	: Interview (\$ )
Report Format :	: Tech. Invs (\$ ) Others
Lump Sum / I.B.I: (\$)	: Weekend (\$
	TOTAL
	TOTAL