

[illegible][illegible]

A white Mercedes-Benz SUV is parked in a garage. The driver-side door is open. The car has a black grille with the Mercedes-Benz logo and a license plate that reads "SGG5918A". To the left, the front of another white car is visible. The garage floor is concrete with a red line and a metal grate. A white pillar and a metal railing are on the right.

https://singapore.merimen.com/claims/index.cfm?fusebox=SVCdoc&fuseaction=dsp_reports&domainid=1&objid=1021532&corole=2&prncoid=200118... 1/6

SGG5918A - Submitted by: Falcon-Air Auto Services Pte Ltd (Sin Ming),



4/17: **Accident Photo** [Linked Accident Report Documents]



5/17: **Accident Photo** [Linked Accident Report Documents]



6/17: **Accident Photo** [Linked Accident Report Documents]


A white Mercedes-Benz SUV is parked in a garage. The car is facing forward, showing its front grille with the Mercedes-Benz logo, headlights, and a black license plate that reads "SGG5918 A". The car is parked next to another white car, which is partially visible on the left. The garage floor is concrete, and there are some items on the right side, including a stack of tires.


A white Mercedes-Benz SUV is parked in a garage. The car is facing forward, and its license plate reads "SGG 5918 A". The garage has a concrete floor and a white wall in the background. There are some cardboard boxes and other items in the background.


SIXTH PLAN

IMPORTANT NOTICE

- Promoter hereby **acknowledges** the details of the accident to signed-up the following persons.
- This Form must be **completed by the Policyholder and/or the Insured Indemnity**.
- Insurance coverage is not an **agreement and does not provide** any actual or constructive warranty of contract. It may allow insurance coverage to **operate within its limits**.
- The time and occurrence of this Form by Insurance companies is not an admission of liability on the part of the Insurance companies.
- Any claims reports may be referred to the Public for Investigation**.
- The report will be forwarded by the Insurers of the Sixteenth Management Centre established by the General Insurance Association of Singapore (GIAS) for writing and the copies of this report will be on file to handle outside upon application by interested parties.
- In the light of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.
- Current under the Personal Data Protection Act (PDPA):
 - Consent, acknowledgment, view and consent first.
 - My/their, my working and the General Insurance Association of Singapore (GIAS) may be permitted to collect, use, disclose and/or process my personal information for the use in this Form and any other personal information provided for me as assigned by my Insurer (including the Personal Information) that I consent and transfer such information to Insurer who has limited liability (including the Insured Indemnity) who has been named and publicly disclosed (as Insured) and be collected, stored and/or "transferred" to the Insurer (hereby, we, the Insurer/Insurers/Insured and my relevant government appointment (including the public), for the purpose(s)) of:
 - promoting, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations involving my Insurers;
 - Investigating the accident and/or my claims;
 - issuing any notice dealing with my Insurers or responding to any enquiries by me;
 - administering my claim including the filing of correspondence, statements, notices, reports or claims to me, which could involve disclosure of certain personal data about me to using delivery of this same as well as on the personal cover of unprocessed claims; and/or
 - complying with applicable law in administering, promoting, handling and/or dealing with my claims (including the "Process");
 - in connection, with those insured (whichever) involved in this accident and the Insurers' Insurers/Insurers, may/ may permitted to collect, use, disclose and/or process my Personal Information for the use more of the above Purpose; and
 - my Personal Information may be disclosed by any of the Insurers and/or claim to be used for any purpose in connection with administering the Insurers' Insurers, which may be used outside of Singapore, for the use or more of the above Purpose.
 - my Personal Information will be collected and used to compile claims history for the purpose of fraud detection, investigation and management to prevent and address claims;
 - the information is collected under all other purposes as shown / disclosed;
 - in all Insurers and/or any other Insurer that would be handling, investigating, controlling or managing their, regulators, law enforcement and government agencies to responsibly respond for the purpose, collect, and
 - for complying with requirements under any regulations, law or court orders.


 Policyholder's Signature
(Name of Insured)


 Insurer's Signature
(Name of Insurer)


 Reporting Centre President's Signature
RAC/RCM/SL

L0000172 (2019/2020)

9/17: **Accident Photo** [Linked Accident Report Documents]

A diagram of a simple neural network. It consists of three layers: an input layer with one node labeled 'A', a hidden layer with one node, and an output layer with one node labeled 'B'. The connections between the input node and the hidden node are labeled with weights S_{11} and S_{12} . The connections between the hidden node and the output node are labeled with weights S_{21} and S_{22} .

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 2105HRS, WHILE I WAS EXITING CAMP TO RETURN TOOM I CRASHED INTO THE BOLLARD (CENTER) THATS LOCATED OUTSIDE THE GUNROOM. THE GUARDS CONDUCTED A ROUTINE BOLLARD TEST W/O DEFENDING A BATTERY TO SERVE AS A WARNING.

DECLARATION
I/We declare the foregoing particulars are true in every respect

72

Policyholder's Signature Date & Time: 2/23/21	Officer's Signature (If driver is not the policyholder) Date & Time:
--	--



10/17: **Accident Photo** [Linked Accident Report Documents]

11/17: **Accident Photo** [Linked Accident Report Documents]

12/17: **Accident Photo** [Linked Accident Report Documents]

SGG5918A - Submitted by: Falcon-Air Auto Services Pte Ltd (Sin Ming),



13/17: **Accident Photo** [Linked Accident Report Documents]



14/17: **Accident Photo** [Linked Accident Report Documents]



15/17: **Accident Photo** [Linked Accident Report Documents]