

SGG5918A - Submitted by: Appraisals Associates Pte Ltd (HQ)



1/125: Front View



2/125: Front View RH



3/125: Front View LH

SGG5918A - Submitted by: Appraisals Associates Pte Ltd (HQ)



4/125: Photos of Damaged Items



5/125: Photos of Damaged Items



6/125: Photos of Damaged Items


SGG5918A - Submitted by: Appraisals Associates Pte Ltd (HQ)



7/125: Photos of Damaged Items



8/125: Photos of Damaged Items



9/125: Photos of Damaged Items

SGG5918A - Submitted by: Appraisals Associates Pte Ltd (HQ)



10/125: Photos of Damaged Items



11/125: Photos of Damaged Items



12/125: Photos of Damaged Items

SGG5918A - Submitted by: Appraisals Associates Pte Ltd (HQ)



13/125: Photos of Damaged Items



14/125: Photos of Damaged Items



15/125: Photos of Damaged Items

SGG5918A - Submitted by: Appraisals Associates Pte Ltd (HQ)



16/125: Photos of Damaged Items



17/125: Photos of Damaged Items



18/125: Photos of Damaged Items

SGG5918A - Submitted by: Appraisals Associates Pte Ltd (HQ)



19/125: Photos of Damaged Items



20/125: Photos of Damaged Items



21/125: Photos of Damaged Items

SGG5918A - Submitted by: Appraisals Associates Pte Ltd (HQ)



22/125: Photos of Damaged Items



23/125: Photos of Damaged Items



24/125: Photos of Damaged Items

SGG5918A - Submitted by: Appraisals Associates Pte Ltd (HQ)



25/125: Photos of Damaged Items



26/125: Photos of Damaged Items



27/125: Photos of Damaged Items

SGG5918A - Submitted by: Appraisals Associates Pte Ltd (HQ)



28/125: Photos of Damaged Items



29/125: Photos of Damaged Items



30/125: Photos of Damaged Items