



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	/Ms Chia Swee Fun
	Reg No/Reg Date	SML2677S / 13/05/2019
	Date In/Mileage	30/06/2022/ 19160
	Chassis No	MMBSTA13AKH001072
	Engine No	3A92UHN8107
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	30/06/2022/ 14:07	DS	303 / Renemer	31330
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
S	MIPNT88088				250.00
	DIAGNOSTIC/SCANNING				
S	MIPNT88088		80		100.00
	TO CHECK ALL LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				
S	MIPNT88088		320		640.00
	TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS				
S	MIPNT88088		11	X	200.00
	TO APPLY SEALANT KIT ON NEW & REPAIR PANELS				
S	MIPNT88088		2240		4480.00
	TO REPLACE EMBLEM, LOGO, LH TAIL LAMP, REAR BUMPER, CLIPS, BRACKETS, BUZZER, ANTENNA, DUCT VENTILATOR & COVER, LH MUDGUARD, LH SPLASHSHIELD, ETC -TO CUT & WELD REAR END PANEL -TO REPAIR REAR BOOT & LHR FENDER STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS				
S	MIPNT98088		1650		2750.00
	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS				
S	MIPNT88088		600		800.00
	TO REMOVE & REPLACE BODY KIT (SPRAY PAINTING & INSTALLATION INCLUDED)				
S	MIPNT88088		sheld		280.00
	REVERSE SENSOR (INCLUDE ITEMS & INSTALLATION)				
S	MIPNT88088		11	X	180.00
	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT				
S	MIPNT88088		11	X	50.00
	WHEEL BALANCING				
S	MIPNT88088		11	X	180.00
	185/55 R18 TYRE				
M	SUNDRY		11	X	50.00
	MIVEC EMBLEM				
M	SUNDRY		11	X	50.00
	C & C LOGO				
M	JJ7415A389	MARK, THREE-DIA	1.00	70.00 0.00	70.00
M	JJ7415A438	MARK, ATTRAGE	1.00	21.00 0.00	21.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info														
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	<table> <tr> <td>Cust No/Name</td><td>/Ms Chia Swee Fun</td></tr> <tr> <td>Reg No/Reg Date</td><td>SML2677S / 13/05/2019</td></tr> <tr> <td>Date In/Mileage</td><td>30/06/2022/ 19160</td></tr> <tr> <td>Chassis No</td><td>MMBSTA13AKH001072</td></tr> <tr> <td>Engine No</td><td>3A92UHN8107</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>A06 / BK</td></tr> </table>	Cust No/Name	/Ms Chia Swee Fun	Reg No/Reg Date	SML2677S / 13/05/2019	Date In/Mileage	30/06/2022/ 19160	Chassis No	MMBSTA13AKH001072	Engine No	3A92UHN8107	Make/Model	MIT/19MY ATTRAGE 1.2 CVT	Colour/Trim	A06 / BK
Cust No/Name	/Ms Chia Swee Fun														
Reg No/Reg Date	SML2677S / 13/05/2019														
Date In/Mileage	30/06/2022/ 19160														
Chassis No	MMBSTA13AKH001072														
Engine No	3A92UHN8107														
Make/Model	MIT/19MY ATTRAGE 1.2 CVT														
Colour/Trim	A06 / BK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	30/06/2022/ 14:07	DS	303 / Renemer	31330

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M JJ8330A851 LH RR LAMP ASSY, COMB <i>cm</i>	1.00	337.00	0.00	337.00
M JJ6410C750 FACE, RR BUMPER <i>Dis</i>	1.00	751.00	0.00	751.00
M JJMU001623 CLIP, BUMPER <i>all</i>	10.00	4.00	0.00	40.00
M JJ6410C433 LH BRACKET, RR BUMPER <i>all</i>	1.00	28.00	0.00	28.00
M JJ6410C434 RH BRACKET, RR BUMPER <i>all</i>	1.00	28.00	0.00	28.00
M JJMZ330600-T69 BODY KIT, ATTRAGE <i>cm</i>	1.00	1643.00	0.00	1643.00
M JJ8637A176 BUZZER, KEYLESS OPERA <i>cm</i>	1.00	91.00	0.00	91.00
M JJ8637B115 ANTENNA, KEYLESS OPER <i>all</i>	1.00	96.00	0.00	96.00
M JJ7835A023 DUCT, RR VENTILATOR x NN	1.00	30.00	0.00	30.00
M JJ7835A032 COVER, RR VENTILATOR x NN	1.00	40.00	0.00	40.00
M JJ5370B565 LH RR, MUD GUARD <i>mus</i>	1.00	36.00	0.00	36.00
M JJ5281A631 PANEL, RR END <i>R</i>	1.00	427.00	0.00	427.00
M JJ7240A172XA TRIM, RR END <i>all</i>	1.00	66.00	0.00	66.00
M JJ5370B295 LH SHIELD, RR WHEEL HO <i>all</i>	1.00	35.00	0.00	35.00

Z NOTES

ACCIDENT ON 29/06/2022 ALONG PIE TOWARDS CHANGI AIRPORT
OWNER CLAIMING THIRD PARTY
REQUIRED REPLACEMENT CAR
TP#: SMG7211X TP INS: CHINA TAIPING

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Authorized signatory and company stamp

Parts	3,739.00
Labour	0.00
Standard Menu	0.00
Specialist Job	9,910.00
Others (Lub, etc)	0.00
Sundry	100.00
Total (w/o GST)	13,749.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name /Ms Chia Swee Fun Reg No/Reg Date SML2677S / 13/05/2019 Date In/Mileage 30/06/2022/ 19160 Chassis No MMBSTA13AKH001072 Engine No 3A92UHN8107 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim A06 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
F0000018	Credit	08/07/2022/ 12:08	DS	303 / Renemer	31330				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
S	MIPNT88088	DIAGNOSTIC/SCANNING							250.00
S	MIPNT88088	TO CHECK ALL LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS							80.00
S	MIPNT88088	TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS							320.00
S	MIPNT88088	TO REPLACE LH TAIL LAMP,REAR BUMPER,CLIPS,LH BRACKET, BUZZER,LH MUD GUARD.							2240.00
		-TO REPAIR LHR FENDER & REAR END PANEL STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS							
S	MIPNT98088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS (LHR FENDER,REAR BUMPER & REAR END PANEL)							1650.00
S	MIPNT88088	TO REMOVE & REPLACE BODY KIT (SPRAY PAINTING & INSTALLATION INCLUDED)							600.00
S	MIPNT88088	REVERSE SENSOR (INCLUDE ITEMS & INSTALLATION)							280.00
X	JJ8330A851	LH RR LAMP ASSY,COMB			1.00	337.00	0.00	337.00	
X	JJ6410C750	FACE,RR BUMPER			1.00	751.00	0.00	751.00	
X	JJMU001623	CLIP,BUMPER			10.00	4.00	0.00	40.00	
X	JJ6410C433	LH BRACKET,RR BUMPER			1.00	28.00	0.00	28.00	
M	JJMZ330600-T69	BODY KIT,ATTRAGE			1.00	1643.00	0.00	1643.00	
X	JJ8637A176	BUZZER,KEYLESS OPERA			1.00	91.00	0.00	91.00	
X	JJ5370B565	LH RR,MUD GUARD			1.00	36.00	0.00	36.00	
Z	NOTES	ACCIDENT ON 29/06/2022 ALONG PIE TOWARDS CHANGI AIRPORT OWNER CLAIMING THIRD PARTY LOSS OF RENTAL (R.A 22888) TP#: SMG7211X TP INS: CHINA TAIPING							
Z	NOTES								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name /Ms Chia Swee Fun Reg No/Reg Date SML2677S / 13/05/2019 Date In/Mileage 30/06/2022/ 19160 Chassis No MMBSTA13AKH001072 Engine No 3A92UHN8107 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim A06 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	08/07/2022/ 12:08	DS	303 / Renemer	31330

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
FINALIZATION (NO. OF TOTAL REPAIR DAYS - 5 DAYS) ATTENTION TO: MR. MARCUS CHUA				
<div style="font-size: 100px; opacity: 0.3;">Estimate</div>				

Confirm & accepted by

Parts	2,926.00
Labour	0.00
Standard Menu	0.00
Specialist Job	5,420.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	8,346.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	30/06/2022 15:34 (SGT)
Reported by	Both
Date of Accident	29/06/2022 18:03 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	Towards Changi Airport
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SML2677S
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CHIA SWEE FUN
NRIC No	SXXXX543G
Email Address	mushroom138@gmail.com
Mobile Phone No	(Phone) +65-90461267
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Attrage
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1193

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	1900096643-02

DRIVER

Name of Driver	YAP ENG SOON
NRIC No	SXXXX180I
Date Of Birth	07/04/1950
Occupation	Indoor

Date Of Driving Pass	01/02/1969
Driving experience	53 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96675218
Alt. Phone Number	-
Email Address	esyap7@gmail.com
Address	15 Meragi Road Singapore
Address complement	-
Postcode	487892
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	CHIA SWEE FUN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO THE ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMG7211X
Vehicle Manufacturer	Honda
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	FAUZEE
Contact Number	(Phone) +65-92219060
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time
Time 30 June 2022 11:35am

Driver's Signature (if driver is not the policyholder) / Date & Time
Time 30 June 2022 11:33am

Witnessed by Reporting Centre Personnel

Sketch Plan



VEHICLE A = SML 2677S

VEHICLE B = SMG 7211X

Describe Circumstances of the Accident

I, Yap Eng Soon, was driving along PIE towards Changi Airport. The cars in front slowed down as it was a slip road and I was also slowing down when vehicle number SMG 7211X (Honda) driven by Mr Fauzee smashed into the rear of my car. Date was 29 June 2022 at about 1803 hours.


Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

30 June 2022
11:34 am.



Driver's Signature (If driver is not the policyholder) / Date & Time

30 June 2022
11:30 am



Witnessed by Reporting Centre Personnel