

REF:

ASSIGNMENT

Veh No: SMY 1002M Yr Regn: 2021 / March.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 C.C 999

Colour Black A/C: Insured / Std / NI / NA

Sp. Reading 13869 . T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAU2228V2LA*017325


Gen. Cond Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

	
N/S	O/S

R: 205/50R16.

Front Rear

R/Bal. 0.1 mm R/Bal. 0.1 mm

L/Bal. 0.1 mm L/Bal. 0.6 mm

D.O.A. D.O.I. 07/07/22

Survey held at Tremonton.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

TP A/G.

mv:

PV:

Nett:

☐: Prel. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Add Fee: : Site insp (\$

Transportation:

Report Formed :

Received 20 March 1998 / Accepted 15 July 1998

Photos

Other:



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GlA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	22/06/2022 17:07 (SGT)
Date of Accident	22/06/2022 08:10 (SGT)
Exact Location of Accident	Pepys Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMY7002M
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHIN DA XING
NRIC No	SXXXX927H
Email Address	Jx.chin@gmail.com
Mobile Phone No	(Phone) +65-93493453
Alternative Phone No	(Office) +65-93493453

VEHICLE PARTICULARS

Manufacturer	Audi
Model	A3
Variant	SEDAN 1.0 TFSI S TRONIC (LED)
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	999

INSURANCE COMPANY

Name of Insurance Company	ERGO Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMPG22003627
Cover Note Number	-

DRIVER

Name of Driver	CHIN JUN XING
NRIC No	SXXXX746Z



Date Of Birth	14/03/1986
Occupation	Outdoor
Date Of Driving Pass	08/06/2021
Driving experience	1 YEAR
Gender	Male
Mobile Number	(Phone) +65-93493453
Alt. Phone Number	-
Email Address	Jx.chin@gmail.com
Address	BLK 7 BEDOK RESERVOIR VIEW #08-01
Address complement	-
Postcode	478929
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Sibling
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 22/06/2022 AT ABOUT 0810HRS, I WAS DRIVING VEHICLE A (SMY7002M) ALONG PEPYS ROAD WHEN SUDDENLY VEHICLE B (SDT3233Y) PROCEED TO GO AGAINST THE FLOW OF TRAFFIC AND STARTED TO REVERSE TO GET INTO THE PARKING LOT WITHOUT LOOKING OUT FOR TRAFFIC. THUS, GRAZED THE LEFT SIDE AND RIM OF MY VEHICLE. NO INJURY.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDT3233Y
Vehicle Manufacturer	Nissan
Vehicle Model	Elgrand
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	KEN
Contact Number	(Phone) +65-97814700

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

ON 22/06/2022 AT ABOUT 0810HRS, I WAS DRIVING VEHICLE A (SMY7002M) ALONG PEPYS ROAD WHEN SUDDENLY VEHICLE B(SDT3233Y) PROCEED TO GO AGAINST THE FLOW OF TRAFFIC AND STARTED TO REVERSE TO GET INTO THE PARKING LOT WITHOUT LOOKING OUT FOR TRAFFIC. THUS, GRAZED THE LEFT SIDE AND RIM OF MY VEHICLE. NO INJURY.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0548/2022/JT
DATE : 1-Jul-22
WIP : 31112

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 07/07/2022

YOUR INSURED VEH NO : SDT 3233 Y

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

OWNER'S NAME : MR CHIN DA XING
ADDRESS : BLK 375 CLEMENTI AVANUE 4
#12-136
SINGAPORE 120375
TELEPHONE : HP +65 93493453
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : DMPG22003627
VEHICLE NO : **SMY 7002 M**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 22/3/2021
ENGINE NO : CHZ C36748
CHASSIS NO : WAUZZZ8V2LA017525
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Jun-22
PLACE OF ACCIDENT : PEPYS ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 7002 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR.HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X.
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	X.
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	500
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	550
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	S/N \$ 280.00	✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,282.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 7002 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Repair</i>	1	\$ 2,433.00	+	
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00	+	
3	FRONT BUMPER GUIDE SECTION - RH	1	\$ 43.00	+	
4	FRONT BUMPER ADAPTER- RH	1	\$ 42.00	+	
5	FRONT BUMPER TRIM COVER - RH	1	\$ 182.00	+	
6	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 571.00	+	
7	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 210.00	+	
8	FRONT FENDER - RH	1	\$ 954.00	+	
9	FRONT FENDER ATTACHMENT PARTS	1	\$ 75.00	+	
10	FRONT FENDER BRACE - RH	1	\$ 107.00	+	
11	FRONT FENDER BRACKET - RH	1	\$ 46.00	+	
12	FRONT FENDER POP RIVET	6	\$ 23.00	+	
13	FRONT WHEEL HOUSING LINER - RH	1	\$ 183.00	+	
14	HEADLIGHT - RH	1	\$ 5,879.00	+	
15	LIFT CYLINDER - RH	1	\$ 156.00	+	
16	LIFT CYLINDER HOSE	1	\$ 78.00	+	
17	ALUMINIUM RIM	1	\$ 1,303.00	+	
18	RUBBER VALVE	4	\$ 15.00	+	
19	SUNDRIES		\$ 350.00	?	

TOTAL SPARE PARTS : \$ 12,845.00

TOTAL LABOUR CHARGES : \$ 5,282.00

GRAND TOTAL : \$ 18,127.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *07/07/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT