
nneth	ASSIGNMENT
From: Date:	Veh No: SLL 63730 Yr Regn: 03,
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD LAP LWS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	(1) Jan
at Workshop m/s EM	Colour M. D. Blue AC: Insured / Std / NI /
of	Sp.Reading 13190 T/Radio: Insured / Std / N1/
Insured:	Eng/No:
Policy No.	CNO: JIAMRC 1890MC200
Claims No.	Gen. Cond: 200d / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder/ Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inprder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / SPD A/Rim or
	Tyre Size: F: 2/5/66 R/7
(Policy Condition)	R:
Remark: The veh had commenced its N/S 0/8	
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 9 mm R/Bal. 9
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 59 mm L/Bal. 59
Est. Repairs: 05 days Res.: Yes or No	D.O.A. 30/6/22 D.O.I. 4/7/2
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt Rear O/S N/S U/C Rooftop or
· Vehicle: IN / OU	
Date: Person Contacted: Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collisi
Date / Time Action / Instruction	
717 1/2m 838301 Condina	(Red. 4074.60,512)
	Jag.,1014.80,31/0)
: Prell. Report	Days Of Repair:5
: Final Report	Resurvey No. of Trip: Survey Fee:
ute/Time, File Return to?	Transporta6:21:
Add Fe	Manager of the state of the sta
	: Interview (\$) Finals
eport Format : TP	: interview (\$) Fortas

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	056D
Vehicle No.:	SLL6373D
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Jul 2022
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	Blue
Manufacturing Year:	2021
Engine No.:	K24W72540031
Chassis No.:	JHMRC1890MC200367
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$35,334.00
Original Registration Date:	29 Mar 2021
First Registration Date:	29 Mar 2021
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$41,468.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Mar 2031
PARF Rebate Amount: Intended COE Rebate Details	\$31,101.00
COE Expiry Date:	28 Mar 2031
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$51,900.00
COE Rebate Amount:	\$43,783.00
Total Rebate Amount:	\$74,884.00

The information contained herein is correct as at 30 Jun 2022



SS2E226U000A / S & H Motor Pte Ltd ENTRY DATE & TIME: 30/06/2022 17:58 (SGT) SUBMITTED BY: Wong Kee Nyuk VERSION: 1 (30/06/2022 17:58 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission

Reported by Date of Accident

Exact Location of Accident

Additional Location Information

Country/State of Loss

30/06/2022 17:58 (SGT)

Both

30/06/2022 11:25 (SGT)

Fifth Ave., Singapore

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLL6373D

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No

Email Address

Mobile Phone No

Alternative Phone No.

No

Melissa Fam Si-Hui

S8690056D

melissafam@gmail.com

(Phone) +65-96697690

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Transmission

CC

Honda Odyssey

Private use

No - Claiming third party

Private car

Auto

2400

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

Tokio Marine Insurance Singapore Ltd

21-MQ001096-R00

DRIVER

Name of Driver

NRIC No

Date Of Birth

Occupation

Accident report SS2E226U000A

Melissa Fam Si-Hui S8690056D 04/08/1986 Indoor

Page 1 of 16

Date Of Driving Pass 11/03/2005 Driving experience 17 YEARS AND 3 MONTHS Gender Female Mobile Number (Phone) +65-96697690 Alt. Phone Number **Email Address** melissafam@gmail.com Address 2 Fifth Ave #03-18 Address complement Postcode 268800 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

refer attached report.

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer

Whitsubishi

Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Category

Name of Driver

Work Permit No

YP1253A

Mitsubishi

Fuso

Commercial vehicle

Commercial vehicle

Jeganathan Raman

G7360829K

Contact Number	(Phone) +65-84253513
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	×

My car stationary at 20% about to turn into che an impact on the Alighted & realised Veh	****				
My car stationary at			*		
	PIFTH	AUX	JUD	dian	4
ons about to turn into	Sintt	BI	u wh	100	
et an impact on the	rager	20		Sasa.	
Alighted & realised Veh	(B) h	100	-1077	6445	1
14 car Took 3 care she	tos L	8 X C	renge	000	ticul
lett the scene			- Ci	9	
				1940 (1940 (1940 (1940 (1940 (1940 (1940 (1940 (1940 (1940 (1940 (1940 (1940 (1940 (1940 (1940 (1940 (1940 (19	and a superior and a superior
			ggreen and a state of the state		#1.200 Mark 10.000 mark 10.000
		27.000000000000000000000000000000000000			
			, o , o , o , o , o , o , o , o , o , o		
			gran and an annual state of the		
					and the second second
				and the second s	
				nederled der in der stelle der st	
decimals and the Control of the Cont			4444		****
		ann to the control of		w.c., 1, 2, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,	
					······································
A. A				***************************************	
				-	****************
	and the second s	annon and announce of the second			n, 1200.000 1100.000.000.000.000.000.000
		075070700+07000000000000000000000000000		Name and the second	
					at the second second second

AND THE PROPERTY OF THE PROPER					
Declaration					
We declare the foregoing particulars are true in every respect.					
- A					
Juliah Welmay		includes the second			and and the
Policyholder's Signature / Date & Time Driver's Signature (if driver is not & Time	the policyholder) / 0		Witnessed by Rep (Name as in NRIC (4 Cur) (0		19C(1)(5)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant dovernment agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date

& Time

Witnessed by Reporting Centre Personnel
(Name as in NRICND card)

Time

No. 11 (Name as in NRICND card)



E M Solution Pte Ltd

160 Sin Ming Drive #03-18/19, Sin Ming Autocity Singapore 575722

Tel: 64560226 Fax: 64584500

GST Reg. No: 201016308K

Not Northwish ESTIMATE

1/Sy & 3850/2

Phermy After Pany
Veh No: SLL 6373D


Make/Model: Honda Odyssey
Chassis No: JHMRC1890MC200367

Melissa Fam Si-Hui 2 Fifth Ave, #03-18 Singapore 268800

Mr

Date of Acc: 30.06.22 TP Veh No: YP 1253A

				ir ven no :	TP 1253A
/No	Qty	Description		Unit Price	Amount
		Materials Rear Boot Lid / 2/6	le.		
1	1 pc	Rear Boot Lid / 1/0	.00		\$ 1,693.00 ~
2	1 pc	Rear Boot Lid Logo			\$ Ma 60.70 -
3	1 pc	Rear Boot Lid Odyssey Em	blem		\$ Me 65.80 -
4	1 pc	Rear Boot Lid Chrome Gar	nish		\$ Pm 201.70 X
5	2 pcs	Rear Boot Lid Reflector La	mp L/R oly Ti	\$ 266.70	\$ 533.40
6	1 pc	Rear Windscreen Mouldin	g 195	,	\$ Me 213.60
7	1 pc	Rear Boot Lid Mechanism	•		\$ 100 281.90
8	1 pc	Rear Boot Lid Inner Trim B	4 4 4	my	400.10 X
9	1 pc		.20		\$ CM 989.00 L
10	2 pcs	Rear Bumper Side Retaine		\$ 35.10	\$ 70.20 X
11	1 pc	Rear Bumper Bracket L/R	1 L/ N		
12	1 pc	Rear Bumper Reinforceme	nt	\$ 40.20	\$ 80.40 X
13		Rear Bumper Chrome Mo		m	\$ 321.40 X
14	1 pc	Rear Bumper Reflector RH		,	132.50
15	1 pc	Rear End Panel	4 18 7		y 200.50 A
16	1 pc		L	me	\$ 405.70
17	1 pc	Rear End Panel Top Garnis		4 405 50	\$ 211.40 7
1/	2 pcs	Reverse Sensor 7-1	6 518 3 year	\$ 405.50	\$ 811.00 4
					\$ 6,538.30
				Less 20% :	\$ 1,307.66
					\$ 5,230.64
1		Special Nett		Parts Total	. 1-
1	1 set	Rear Bumper Clips			\$ 1/4 45.00
2	1 set	Rear End Panel Top Garnish	Clips		\$ Mec 35.00 7
3	1 set	Rear Boot Lid Trim Clips			\$ 45.00 X
4	1 pc	Windscreen Sealant			\$ Ma 50.00 4
				Special Nett :	\$ 175.00
		<u>Labour</u>			
1		& rearrange electrical wirings, ch			\$ 80.00 2
2		& replace upholstry, cushion seat	: & trim garnishes.		
3		, reinstal rear windscreen.			\$ 100.00 / \$ 200.00 /
4	To remove,	transfer boot lid components	11/1/0		ć 00.00 d
5	To remove,	repair & replace damaged body	parts and where isultant	s hence notify	
		to the accident.	une repairer of the fo	lowing.	\$ 800.00 6
6	Putty and r	espray painting on affected porti	• 10 resurvey before/after s	Spray painting	\$ 800.00
,		& renew reverse sensor	 Io display damaged part(s) during resurvey	\$ 100.00 5
8		ng on affected portions.	Parts prices are subject to	Confirmation	
	nast proon	directed portions.	Third party survey is on a No illegal modification(s) i	"Without Prejudice" basis	\$ 2,240.00
			Supplementarion(s)	is allowed	2,240.00
			Supplementary item(s) mu is subject to final apportal	ist he recurrened and	
				- an cases and 9 of hpan	7,043.04
	()		Acknowledged by Repairer		
	Ma		Signature:		



Signature:

Page 1 of 1

Date:

E M Solution Pte Ltd

160 Sin Ming Drive #03-18/19, Sin Ming Autocity Singapore 575722 Tel: 64560226 Fax: 64584500

GST Reg. No: 201016308K

Supplementary

Date: 4th July 2022

Mr

Melissa Fam Si-Hui

2 Fifth Ave, #03-18 Singapore 268800 Veh No: SLL 6373D

Make/Model: **Honda Odyssey** Chassis No: JHMRC1890MC200367

Date of Acc: 30.06.22 TP Veh No: YP 1253A

Parts Total : \$

278.96

S/No	Qty	Description	Unit Price	Amount
		Materials		2/2
1	1 pc	Rear Boot Weatherstrip		\$011/10 175.40 L
2	1 pc	Rear Bumper Keyless Antenna		\$ 70.10
3	1 pc	Rear Bumper Alarm Sensor		\$ \in 95.20 X
				\$ 348.70
			Less 20%	· \$ 69.71

8

for E M Solution Pte Ltd