(08/11/13) wef

ASS. REC. BY: Marcus

REF: CC6/AIG22006336/Up93

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLR 66864

at Workshop m/s Falcon Air Cargo

of

Insured: SLB2777B

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: $50K.

IDAC Accident Rport: Consistent? : **Yes** or **No**

GIA / PR Seen: Consistent? : **Yes** or **No**

Est. Repairs: 4 days Res.: **Yes** or **No**

Lum Sum: 20 % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS 024G

Vehicle: **IN / OUT**

Date: Person Contacted: 97852257

Veh No: SLR 66864 Yr Regn: 20/05/09

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer** or CA/

Make: Audi A6 c.c 1984

Colour Silver A/C: **Insured / Std / NI / NA**

Sp.Reading 224926 T/Radio: **Insured / Std / NI / NA**

Eng/No:

C/No: WAUZZZ4F29N046961

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or

Brake: **Inorder / Jammed / Leaked / Burnt** or

Modi : **Nil / S/Rim / STD A/Rim** or

Tyre Size: F: 225/50 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	2/7/22	D.O.I.	04/07/22

Survey held at

Des. of Damages : **Frt / Rear / O/S / N/S / U/C / Rooftop** or Rear

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	Rep $K.
	COE until 31-03-2029
26/7/22	L/S $7700 informed Jerol

Date/Time, File **Pass** to? ☐ : **Preli. Report**

1) ☐ : **Final Report**

Date/Time, File **Return** to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($) __S + RS, __SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

TOTAL

Report Format :

Lump Sum / I.B.I: ($)