

ASS. REC. BY:

REF:

262/ 22006356/KC

C

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLA 3604R

Yr Regn:

02, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy ALIAS

c.c.

1598

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

128925

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MRC53REH-104540264

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

30/6/22

D.O.I.

4/7/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/7 July @ 2800. Car had been Cled. #329-74,60%

Date/Time, File Pass to?



: Prell. Report



: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fines

Others

TOTAL

Report Format :

TP

Lump Sum / I.B.I: (\$

2800

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	462I
<b>Vehicle Details</b>	
Vehicle No.:	SLA3604R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Jul 2022
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1ZRY219485
Chassis No.:	MR053REH104540264
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,804.00
Original Registration Date:	27 Feb 2016
First Registration Date:	27 Feb 2016
Transfer Count:	0
Actual ARF Paid:	\$17,804.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Feb 2026
PARF Rebate Amount:	\$11,572.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	26 Feb 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$43,000.00
COE Rebate Amount:	\$15,689.00
<b>Total Rebate Amount:</b>	<b>\$27,261.00</b>

The information contained herein is correct as at 01 Jul 2022

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	30/06/2022 17:33 (SGT)
Reported by	Both
Date of Accident	30/06/2022 08:45 (SGT)
Exact Location of Accident	Boon Lay Way, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA3604R
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ROY ANG CHONG WEI
NRIC No	S7343462I
Email Address	royangchongwei@gmail.com
Mobile Phone No	(Phone) +65-91469630
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1600

#### INSURANCE COMPANY

Name of Insurance Company	Singapore Life Ltd
Policy Number / Cover Note Number	10813741

#### DRIVER

Name of Driver	ROY ANG CHONG WEI
NRIC No	S7343462I
Date Of Birth	08/12/1973
Occupation	Indoor

# SKETCH PLAN


## SKETCH PLAN


### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 30/4/22  
 12:17pm  
 Policyholder's Signature / Date & Time

  
 Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan





Describe Circumstances of the Accident

ON 30 June 2022  
 Morning at 8:45am at the traffic light junction  
 along Boon Lay Way and Business Park Road  
 at the My car was stationary as it was red  
 light. Before I was about to drive off,  
 A lorry knocked my rear.  
 we drove to the side of the road to  
 exchange particulars and took photos.

Declaration

We declare the foregoing particulars are true in every respect.

 30 Jun, 2022  
 12:20pm  
 Policyholder's Signature / Date &  
 Time

  
 Driver's Signature (If driver is not the policyholder) / Date  
 & Time

Witnessed by Reporting Centre  
 Personnel

# NGS AUTOMOTIVE

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047  
Tel: 64815727 Fax: 64815772 Email: evelyn1911ngsautomotive@gmail.com  
Reg No.: 53405718K

## QUOTATION

No. : AQT-0064

ERGO INSURANCE PTE LTD

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Your Ref. : CDMCG22001268

Our Ref : AQT-0064/SLA3604

C. C. :

Date : 01/07/2022

Page : 1 of 2

TEL : 6829 9194 SURVEY FAX :

Description	Qty	U/ Price	Amount
		S\$	S\$
ACCIDENT ON 30/6/22 @8:45HRS ALONG BOON LAY WAY INVOLVING SLA3604R/GBE8059D			
REPLACEMENT PARTS			
REAR BOOT LID	1	783.90	783.90
BOT LAMP RH/LH	2	293.18	586.36
TAILLAMP RH/LH	2	385.80	771.60
REAR BUMPER	1	573.30	573.30
REINFORCEMENT, RR BUMPER	1	336.20	336.20
ARM, REAR BUMPER RH/LH	2	60.80	121.60
RETAINER RH/LH UPP	2	71.70	143.40
RETAINER SIDE RH/LH	2	70.00	140.00
END PANEL	1	655.60	655.60
END PANEL GARNISH	1	236.50	236.50
LUGGAGE COMPARTMENT PANEL - REPAIR			
RUBBER, TRUNK	1	196.88	196.88
REVER, SENSOR RH/LH SET	1	499.62	499.62
EMBLEM 'BADGE'	1	59.00	59.00
EMBLEM 'CORROLA'	1	56.70	56.70
EBLEM 'ALTIS'	1	62.00	62.00
LOCK, RR BOOT INNER	1	357.00	357.00
CLIPS, RR TRIM	20	5.00	100.00
SubTotal			5,679.66
LESS 25%	1	-1,419.92	-1,419.92
NO PLATE C/W CASING S.NET	1	50.00	50.00
TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENT/ATTACHMENT, REPAIR/RESHAP DENTED BODY PANEL	1	1,400.00	1,400.00

*Not Authorised  
C/Pay @ 2800h  
Running After Rain  
4 days*

*015 61*

*(Original) C198-00*

*285-10*

*258*

# NGS AUTOMOTIVE

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047  
Tel: 64815727 Fax: 64815772 Email: evelyn1911ngsautomotive@gmail.com  
Reg No.: 53405718K

## QUOTATION

No. : AQT-0064

ERGO INSURANCE PTE LTD

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

TEL : 6829 9194 SURVEY FAX :

Your Ref. : CDMCG22001268  
Our Ref : AQT-0064/SLA3604  
C. C. :  
Date : 01/07/2022  
Page : 2 of 2

Description	Qty	U/ Price S\$	Amount S\$
REPAIR/RESHAPR DENTED BODY PANEL. REPLACE DAMAGED PART. REFIT INTO POSITION.			
TRANSFER TAILGATE MECHANISM	1	180.00 <i>501</i>	180.00
SPRAY PAINTING	1	1,200.00 <i>6001</i>	1,200.00
TO CHECK ALL WIRE HARNESS, ALL RELATED CONNECTORS. CHECK PROPER FUNCTION.	1	40.00 <i>201</i>	40.00

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Any other parts which necessitate repair or renewal will incur additional charged.  
Please contact our Ms Evelyn @ HP 96955547 to arrange for survey. Thank you.

Total

**7,129.74**

Yours faithfully,



EVELYN