




Service Request Details

Claim

S2M045UT

Reference

None 

Loss Date

2 July 2022

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

5 Jul 2022 9:28:41 AM

Request Date

5 July 2022

Due Date

13 July 2022

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

Accept Work

Vehicle Information

Incident Vehicle Registration #
SLN9561Y

Make
TPVD BMW

Model
X1

Service Address

, , ,

Primary Contact/Insured

CITYCAB PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

ONG Kian Theng Derick


derick.ongkt@axa.com.sg


Additional Instructions


Document SubType


+ Upload Documents

Already Attached

NAME	 EMAIL TP REG.pdf.pdf
TYPE	Other
SUBTYPE	Other
AUTHOR	do not reply
DATE UPLOADED	

NAME	 SURVEYOR APPOINTED.msg.msg
TYPE	Letters and Correspondence
SUBTYPE	Solicitor / Advocate
AUTHOR	VISHNU BATHAM Shekhar
DATE UPLOADED	5 July 2022

NAME	 SLN9561Y (Tokio) GIA.pdf.pdf
TYPE	Reports & Statement
SUBTYPE	GIA Report
AUTHOR	VISHNU BATHAM Shekhar
DATE UPLOADED	5 July 2022

NAME	 EMAIL TP REG.pdf.pdf
TYPE	Letters and Correspondence
SUBTYPE	Solicitor / Advocate
AUTHOR	VISHNU BATHAM Shekhar
DATE UPLOADED	5 July 2022

FILE	reports & statement
SUBTYPE	GIA Report
AUTHOR	VISHNU BATHAM Shekhar
DATE UPLOADED	5 July 2022
