



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22006386/Uvy3m4	
			Date: 13/07/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBK 5877Y	Veh. Inspected	SJB 1280Y
	Policy No.	D21MTMC01005342	Coverage (\$)	0.00
	Claim No.	CMTD2202274/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	05/07/2022
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN PASSAT B8 (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WVWZZZ3CZGE059220	Colour	GREY
	Odometer	75411 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 ZR17	MICHELIN	7 mm
	L/H Front Tyre	215/55 ZR17	MICHELIN	7 mm
	R/H Rear Tyre	215/55 ZR17	MICHELIN	7 mm
	L/H Rear Tyre	215/55 ZR17	MICHELIN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/06/2022	Inspection Date	05/07/2022
	Survey held at	39 Woodlands Close, MEGA@Woodlands #01-24		
	Repairer	NINETEEN AUTOWERKS PTE. LTD.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	