



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                           |                 |                          |  |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------|-----------------|--------------------------|--|
| SOMPO INSURANCE SINGAPORE PL<br>50 RAFFLES PLACE #03-03<br>SINGAPORE LAND TOWERSINGAPORE 048623                                        |                                           |                 | Ref: CS/SMO22006386/Uvy3 |  |
|                                                                                                                                        |                                           |                 | Date: 05/07/2022         |  |
|                                                                                                                                        |                                           |                 | Code: SMO                |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                           |                 |                          |  |
| Insured Veh.                                                                                                                           | FBK 5877Y                                 | Veh. Inspected  | SJB 1280Y                |  |
| Policy No.                                                                                                                             |                                           | Coverage (\$)   | 0.00                     |  |
| Claim No.                                                                                                                              | CMTD2202274/THE                           | Excess (\$)     | 0.00                     |  |
| Assign From                                                                                                                            | GRACE TEO                                 | Assign Date     | 05/07/2022               |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                           |                 |                          |  |
| Make & Model                                                                                                                           |                                           | c.c             | 0                        |  |
| Engine No.                                                                                                                             | HIDDEN                                    | Year of Reg.    |                          |  |
| Chassis No.                                                                                                                            |                                           | Colour          |                          |  |
| Odometer                                                                                                                               | -                                         | Steering        |                          |  |
| Brakes                                                                                                                                 |                                           | Modification    |                          |  |
| General                                                                                                                                |                                           |                 |                          |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                           |                 |                          |  |
|                                                                                                                                        | Size                                      | Make            | Balance                  |  |
| R/H Front Tyre                                                                                                                         |                                           |                 | mm                       |  |
| L/H Front Tyre                                                                                                                         |                                           |                 | mm                       |  |
| R/H Rear Tyre                                                                                                                          |                                           |                 | mm                       |  |
| L/H Rear Tyre                                                                                                                          |                                           |                 | mm                       |  |
| <b>4. Description of Damages</b>                                                                                                       |                                           |                 |                          |  |
|                                                                                                                                        |                                           |                 |                          |  |
| <b>5. General Information</b>                                                                                                          |                                           |                 |                          |  |
| Accident Date                                                                                                                          | 29/06/2022                                | Inspection Date | 05/07/2022               |  |
| Survey held at                                                                                                                         | 39 Woodlands Close, MEGA@Woodlands #01-24 |                 |                          |  |
| Repairer                                                                                                                               | NINETEEN AUTOWERKS PTE. LTD.              |                 |                          |  |
| <b>5a. Remarks</b>                                                                                                                     |                                           |                 |                          |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                           |                 |                          |  |