

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA	DATE	: 6-Jul-22
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJJ6656Y	Xiao Tony	
MODEL	: TOYOTA VIOS		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 5-Jul-22
		TIME	: 1422HRS
THIRD PARTY REQUESTOR / CONTACT	:	JACK LI	

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT FENDER <i>Dented</i>	1	\$ 533.20	\$ 533.20
2	FRONT FENDER EMBLEM <i>new</i>	1	\$ 60.00	\$ 60.00
3	FRONT DOOR RH <i>Dented</i>	1	\$ 869.40	\$ 869.40
4	FRONT DOOR PROTECTOR <i>new</i>	1	\$ 155.20	\$ 155.20

1462.60

1086.95

TOTAL PRICE \$ 1,617.80

LESS 25% \$ 404.45

SUB TOTAL PRICE \$ 1,213.35

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	SIDE SKIRT <i>torn</i>	1	\$ 1,200.00	\$ 1,200.00
2	FRONT FENDER STICKER <i>new</i>	1	\$ 120.00	\$ 120.00
3	DOOR JAPAN STICKER <i>new</i>	1	\$ 120.00	\$ 120.00
4	WHEEL RIM <i>new</i>	1	\$ 1,500.00	\$ 1,500.00

TOTAL \$ 2,940.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	400	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	600	
3	TUFF COAT	\$ 250.00	40.	
4	WIRING CHECK	\$ 120.00	30	
5	TO REMOVE AND REFIX FRONT DOOR MECHANISM	\$ 140.00	60.	
6	FOUR WHEEL ALIGHMENT	\$ 100.00	x	

TOTAL

\$2,610.00

1130

ESTIMATE REPORT

TOTAL PARTS COST : \$ 4,153.35
TOTAL LABOUR COST : \$ 2,610.00
TOTAL REPAIR COST : \$ 6,763.35

APPROVED DETAILS

SURVEYOR :
CONTACT NO :
PART BY PART / LUMP SUM :
NO OF DAYS :

FAX :

Adrian L

h/c 06/07/22.

0.4 days.

total: 2816.95

h/s: 2-21c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: