

ASS. REC. BY:

REF:

AGZ/22 008471/KC

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

8160k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SBR 9696P

Yr Regn:

02 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Porsche

Macan

C.C

1984

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

74079

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WPI 882958-GLB13462

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / RIM or

Tyre Size:

F:

265/40R21

R:

295/35R21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

2/7/22

D.O.I.

5/9/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

F. + S.

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M/s : **Auto & General Insurance (Singapore) Pte Ltd**
190, Clemenceau Avenue, #03-01,
Singapore Shopping Centre,
Singapore 239924

Attn :
Tel : Motor Claims Department
Fax : 6221 2111
6725 0611

Estimate bill : TT 22 / 22 / TP / WT

Registration No : SBR9696P

Make / model : Porsche Macan 2.0

Mileage :

Date : 16 / 08 / 2022

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SLS4103T AND SBR9696P ALONG BLK 264 SERANGOON CENTRAL HDB CARPARK ON 02 JULY 2022 AT ABOUT 1640HRS.

1pc	Front bonnet	\$	8,992.00	X
1pc	Front LH head lamp	\$	5,495.00	X
1pc	Front bumper	\$	3,237.00	X
1pc	Front bumper lamp (LH)	\$	508.00	X
2pcs	Front bumper side grille (LH)	\$	222.00	X
2pcs	Front bumper side grille covering (LH)	\$	221.00	X
2pcs	Front bumper side grille fin (LH)	(Each \$135.00) \$	270.00	X
2pcs	Front bumper side grille garnish (LH)	\$	149.00	X
1pc	Front bumper fog lamp outer cover (LH)	\$	98.00	X
1pc	Front bumper side retainer (LH)	\$	383.00	X
	Sub total :	\$	19,575.00	
	Less 10% discount :	\$	1,957.50	
	A total :	\$	17,617.50	

Remove & transfer front bonnet necessary attachment spare parts item.

Remove & transfer front bumper necessary attachment spare parts item.

Remove and refit front bonnet, front LH head-lamp, front bumper, front bumper lamp (LH), front bumper side grille (LH), front bumper side grille covering (LH), front bumper side grille fins (LH), front bumper side grille garnish (LH), front bumper side retainer (LH). Front bumper fog lamp outer cover (LH),

Heat / weld / beating / pull / straighten / align front chassis frame by Chassis Alignment Jack.

To check and refit front head-lamp (Left & right).

Total amount of Page 1 :

\$ 1,500.00
\$ 150.00
\$ 19,267.50

Tropical Tech Automobile Services

(Authorised Signature)
William Tan



NOT WORKING
11 hrs &
Running After Paint
4 days

Page 1 of 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M/s : **Auto & General Insurance (Singapore) Pte Ltd**
190, Clemenceau Avenue, #03-01,
Singapore Shopping Centre,
Singapore 239924

Attn :
Tel : Motor Claims Department
Fax : 6221 2111
6725 0611

Estimate bill : TT 22 / 22 / TP / WT

Registration No : SBR9696P

Make / model : Porsche Macan 2.0

Mileage :

Date : 16 / 08 / 2022


**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SLS4103T AND SBR9696P ALONG
BLK 264 SERANGOON CENTRAL HDB CARPARK ON 02 JULY 2022 AT ABOUT 1640HRS.**

Diagnostic front bumper parktronic sensor fault error by HHT	\$	120.00	7
Under coating on front damaged portion.	\$	200.00	X
Putty / primer application, spray painting on front bonnet, front bumper (Pearl White).	\$	1,800.00	
Balance amount brought from Page 1 :	\$	19,267.50	
Grand final amount :	\$	21,387.50	

Tropical Tech Automobile Services


(Authorised Signature)
William Tan

Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2nd July 2022 at 1640 hrs, I parked my car at the multi storey car park next to NEX shopping mall. While I was out side my car, I saw a Toyota Sienna reverse towards my car. I shouted at the driver to stop but he still hit onto my car front left side. Afterwards we exchanged particulars and the driver told me to claim from his insurance company.

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature

Name:
NRIC/ID No.

() Claim Own Policy () Claim Third Party () Reporting Only
(x) Claim OD/TP at other workshop